Tru64 UNIX 4.0F and TruCluster 1.6 Patch Summary and Palease Notes for Patch Kit-0006
Patch Summary and Release Notes for Patch Kit-0006
h.h. 9994
July 2001
This manual describes the release notes and contents of Patch Kit-0006. It provides any special instructions for installing individual patches.
For information about installing or removing patches, baselining, and general patch management, see the <i>Patch Kit Installation Instructions</i> .

© 2001 Compaq Computer Corporation

COMPAQ, the Compaq logo, AlphaServer, TruCluster, ULTRIX, and VAX Registered in U.S. Patent and Trademark Office. Alpha and Tru64 are trademarks of Compaq Information Technologies Group, L.P.

Motif, OSF/1, UNIX, X/Open, and The Open Group are trademarks of The Open Group.

All other product names mentioned herein may be trademarks or registered trademarks of their respective companies.

Confidential computer software. Valid license from Compaq required for possession, use, or copying. Consistent with FAR 12.211 and 12.212, Commercial Computer Software, Computer Software Documentation, and Technical Data for Commercial Items are licensed to the U.S. Government under vendor's standard commercial license.

Compaq shall not be liable for technical or editorial errors or omissions contained herein. The information in this document is provided "as is" without warranty of any kind and is subject to change without notice. The warranties for Compaq products are set forth in the express limited warranty statements accompanying such products. Nothing herein should be construed as constituting an additional warranty.

Contents

About This Manual

1	Releas	se Notes	
	1.1	Patch Process Resources	1-
	1.2	Required Storage Space	1-
	1.3	Release Note for TruCluster Server	1–2
	1.4	Release Note for Tru64 UNIX Patch 651.00	1–2
	1.5	Release Note for Tru64 UNIX Patches 680.00 and 682.00	1–2
	1.6	Release Notes for Tru64 UNIX Patch 640.00	1–3
	1.6.1	mountd Reference Page Update	1–3
	1.6.2	UFS Delayed Metadata mount Option	1–3
	1.6.3	3DLabs Oxygen VXI Graphics Card	1–3
	1.6.4	PCI To Ethernet/Graphics Combo Adapter (3X-DEPVD-AA)	1-4
	1.6.5	DEGPA-TA Gigabit Ethernet Device	1-4
	1.6.6	Intelligent I/O Disks with mnemonic ri	1–4
	1.6.7	Virtual Memory Problem	1–5
	1.6.8	PCI To Ethernet/Graphics Combo Adapter	1–6
	1.6.9	Pleiades II Switches	1–6
	1.6.10	I/O Throttling/Smooth Sync	1-7
	1.6.11	Granularity Hint Regions Restriction Removal	1–9
	1.7	Release Note for DEC 7000 Upgrades to AlphaServer 8400	1–10
	1.8	Release Notes for Tru64 UNIX Patches 476.00 and 351.00	1–10
	1.8.1	Visual Threads Upgrade Required	1–10
	1.8.2	quotacheck(8), fsck(8), and fstab(4) Reference Pages	1–10
	1.9	Release Note for Patch 315.00	1–13
	1.10	Release Note for Patch 351.00	1-14
	1.11	Release Notes for Tru64 UNIX Patch 713.00	1-14
	1.12	Release Note for Tru64 UNIX Patch 592.00	1-14
	1.13	Release Note for TruCluster DRD Workaround	1–1
2	Summ	ary of Base Operating System Patches	
3	Summ	ary of TruCluster Software Patches	
Та	bles		
	2–1	Updated Base Operating System Patches	2-
	2–2	Summary of Base Operating System Patches	2-2
	3–1	Updated TruCluster Software Patches	3–
	3–2	Summary of TruCluster Patches	3–

About This Manual

This manual contains information specific to Patch Kit-0006 for the Tru64 UNIX™ Version 4.0F operating system and TruCluster™ 1.6 server software product. It provides a list of the patches contained in each kit and describes any information you need to know when installing specific patches.

For information about installing or removing patches, baselining, and general patch management, see the Patch Kit Installation Instructions.

Audience

This manual is for anyone who installs and removes the patch kit and who manages patches after they are installed.

Organization

This manual is organized as follows:

- *Chapter 1* Contains the release notes for this patch kit.
- Chapter 2 Summarizes the base operating system patches included in the kit.
- Summarizes the TruCluster software patches included in the kit.

Related Documentation

In addition to this manual, you should be familiar with the concepts and mechanisms described in the following Tru64 UNIX and TruCluster (TCR) documents:

- Tru64 UNIX and TCR Patch Kit Installation Instructions
- Tru64 UNIX Installation
- Tru64 UNIX Administration
- TruCluster Software Products Software Installation
- TruCluster Software Products Cluster Administration
- dupatch(8) Reference Page
- Release-specific installation documentation

Reader's Comments

Compaq welcomes any comments and suggestions you have on this and other Tru64 UNIX manuals.

You can send your comments in the following ways:

- Fax: 603-884-0120 Attn: UBPG Publications, ZK03-3/Y32
- Internet electronic mail: readers comment@zk3.dec.com

A Reader's Comment form is located on your system in the following location:

/usr/doc/readers_comment.txt

Mail:

Compaq Computer Corporation UBPG Publications Manager ZK03-3/Y32 110 Spit Brook Road Nashua, NH 03062-9987

Please include the following information along with your comments:

- The full title of this document.
- The section numbers and page numbers of the information on which you are commenting.
- The version of Tru64 UNIX that you are using.
- The version of TruCluster software that you are using.
- If known, the type of processor that is running the Tru64 UNIX software.

The Tru64 UNIX Publications group cannot respond to system problems or technical support inquiries. Please address technical questions to your local system vendor or to the appropriate Compaq technical support office. Information provided with the software media explains how to send problem reports to Compaq.

Release Notes

This chapter provides information that you must be aware of when working with Tru64 UNIX 4.0F and TCR 1.6 Patch Kit-0006.

1.1 Patch Process Resources

Compaq provides Web sites to help you with the patching process:

- To obtain the lastest patch kit for your operating system and cluster:
 - http://ftpl.support.compaq.com/public/unix/
- To view or print the lastest version of the *Patch Kit Installation Instructions* or the *Patch Summary and Release Notes* for a specific patch kit:
 - http://www.tru64unix.compaq.com/faqs/publications/patch/
- To visit Compaq's main support page:
 - http://www.compaq.com/support/index.shtml
- To visit the Tru64 UNIX homepage:
 - http://www.tru64unix.compaq.com/

1.2 Required Storage Space

The following storage space is required to successfully install this patch kit:

Base Operating System

- Temporary Storage Space
 - A total of ~250 MB of storage space is required to untar this patch kit. It is recommended that this kit not be placed in the /, /usr, or /var file systems because this may unduly constrain the available storage space for the patching activity.
- Permanent Storage Space
 - Up to ~63 MB of storage space in /var/adm/patch/backup may be required for archived original files if you choose to install and revert all patches. See the *Patch Kit Installation Instructions* for more information.
 - Up to ${\sim}64$ MB of storage space in /var/adm/patch may be required for original files if you choose to install and revert all patches. See *Patch Kit Installation Instructions* for more information.
 - Up to ~ 1190 KB of storage space is required in /var/adm/patch/doc for patch abstract and README documentation.
 - A total of $\sim\!160~KB$ of storage space is needed in /usr/sbin/dupatch for the patch management utility.

TruCluster Software Products

- Temporary Storage Space
 - A total of \sim 250 MB of storage space is required to untar this patch kit. It is recommended that this kit not be placed in the /, /usr, or /var file systems

because this may unduly constrain the available storage space for the patching activity.

Permanent Storage Space

Up to ~44.5 MB of storage space in /var/adm/patch/backup may be required for archived original files if you choose to install and revert all patches. See the *Patch Kit Installation Instructions* for more information.

Up to ~46 MB of storage space in /var/adm/patch may be required for original files if you choose to install and revert all patches. See the *Patch Kit Installation Instructions* for more information.

Up to ~1236 KB of storage space is required in /var/adm/patch/doc for patch abstract and README documentation.

A total of $\sim \! 168 \; KB$ of storage space is needed in /usr/sbin/dupatch for the patch management utility.

1.3 Release Note for TruCluster Server

If you are installing only TCR patches, you MUST rebuild the kernel and reboot the machine for the changes to take effect. If removing only TCR patches, you MUST also rebuild the kernel and reboot the machine for the changes to take effect.

1.4 Release Note for Tru64 UNIX Patch 651.00

This patch contains changes to the $\verb"rexecd"$ reference page.

OPTIONS

-s Causes rexect to check for the ptys keyword in the /etc/securettys file and to deny execution of the request if it is from root and on a pseudoterminal.

DESCRIPTION

6. The rexect server then validates the user as is done at login time and, if started with the -s option, verifies that the /etc/securettys file is not setup to deny the user. If the authentication was successful, rexect changes to the user's home directory, and establishes the user and group protections for the user. If any of these steps fail, the connection is aborted with a diagnostic message returned.

1.5 Release Note for Tru64 UNIX Patches 680.00 and 682.00

This patch delivers version V1.0-032 of the libots3 library. Version 2.0 of the libots3 library is delivered with the Compaq FORTRAN Compiler, Versions 5.3 ECO1 and 5.4, or the Developers Tool Kit (DTK) (OTABASE subset). If libots3 V2.0 is already installed on your system, and you install this patch, you will receive the following informational message:

Problem installing:

- Tru64_UNIX_V4.0G / Software Development Environment Patches:

Patch 00XXX.00 - Fix for parallel processing support library

./usr/shlib/libots3.so: is installed by:

OTABASE212 and can not be replaced by this patch.

This patch will not be installed.

To determine what version of libots3 library is installed on your system, execute the following command:

what /usr/shlib/libots3.so

```
libots3.so:
libots3.a V2.0-094 GEM 27 Feb 2001
```

1.6 Release Notes for Tru64 UNIX Patch 640.00

This section contains release notes for Patch 640.00.

1.6.1 mountd Reference Page Update

```
The following is an update for the mountd reference page.
```

```
SYNOPSIS mountd [-d] [-i] [-n] [-s] [-r] [-R] [exportsfile]
```

FLAGS

- -r Have mountd listen for requests on a reserved port. This is the default behavior.
- -R mountd may listen on an unreserved port.

1.6.2 UFS Delayed Metadata mount Option

This new mount option allows for disabling synchronous metadata writes on a specified filesystem. The new mount option name is delayed.

To maintain the file system's consistency, UFS metadata (such as inode, directory, and indirect blocks) is updated synchronously by default.

Metadata updates are typically performed synchronously to prevent filesystem corruption after a crash. The trade-off for this filesystem integrity, however, is performance. In some cases, such as a filesystem serving as a cache, performance (faster metadata update) is more important than preserving data consistency across a system crash; for example, files under /tmp or web proxy servers such as Squid.

This means two things. One is that multiple updates to one block becomes only one block write, as opposed to multiple writes of the same block with traditional synchronous metadata update. The other is that users can experience much better responsiveness when they run metadata intensive applications because metadata writes will not go out to the disk immediately while users get their prompt back as soon as the metadata updates are queued.

This delayed option should not be used on the / or /usr filesystems. It should be used only on filesystems that do not need to survive across a system crash.

To enable the delayed option, run:

```
mount -o delayed

or

mount -u -o delayed mount -u -o delayed
```

1.6.3 3DLabs Oxygen VXI Graphics Card

This patch provides the driver support for the 3DLabs Oxygen VX1 graphics card. In order to obtain full support for this graphics card, you must also select Patch 713.00, which is the X server portion of the patch.

If you have a system with this new graphics card, you will need to reconfigure and rebuild the kernel after installing this patch.

To reconfigure and rebuild the kernel, follow these steps:

1. Shut down the system:

- # /usr/sbin/shutdown -h now
- 2. Boot genymunix to single-user mode:

```
>>> boot -fi genvmunix -fl s
```

- 3. After the system boots to single-user mode, mount the file systems, run the update command, and activate the swap partition:
 - # sbin/bcheckrc
 - #/sbin/update
 - #/sbin/update
- 4. Run doconfig to create a new kernel configuration file and rebuild the kernel:
 - # /usr/sbin/doconfig

 Note	

Do not specify the -c option to doconfig. If you do, doconfig will use the existing kernel configuration file which will not have the appropriate controller entry for the 3DLabs Oxygen VX1 graphics card.

- 5. Save the old /vmunix file and move the new kernel to /vmunix.
- 6. Shut down the system:
 - # /usr/sbin/shutdown -h now
- 7. Boot the new kernel:
 - >>> boot

If you remove this patch from your system after you have rebuilt the kernel to incorporate support for the 3DLabs Oxygen VX1 graphics card as described you will need to rebuild the kernel again to restore generic VGA graphics support. To do this, follow the steps given previously. The doconfig utility running on the original, unpatched <code>genvmunix</code> will not recognize the 3DLabs Oxygen VX1 graphics card and will include generic VGA graphics support in the resulting kernel.

1.6.4 PCI To Ethernet/Graphics Combo Adapter (3X-DEPVD-AA)

This patch provides the driver support for the PCI To Ethernet/Graphics Combo Adapter (3X-DEPVD-AA) (also known as the ITI6021E Fast Ethernet NIC 3D Video Combination Adapter, InterServer Combo, or JIB). To obtain full support for the PCI To Ethernet/Graphics Combo Adapter (3X-DEPVD-AA), you must also select Patch 709.00, which is the X server portion of the patch.

1.6.5 DEGPA-TA Gigabit Ethernet Device

This patch provides support for DEGPA-TA (1000BaseT) Gigabit Ethernet device. If you have a system with this new Ethernet device, you will need to reconfigure and rebuild the kernel after installing this patch.

To do this, follow these steps:

- 1. Shut down the system:
 - # /usr/sbin/shutdown -h now
- 2. Boot genvmunix to single-user mode:
 - >>> boot -fi genvmunix -fl s

- 3. After the system boots to single-user mode, mount the file systems, run the update command, and activate the swap partition:
 - # /sbin/bcheckrc
 - # /sbin/update
 - #/sbin/swapon -a
- 4. Run doconfig to create a new kernel configuration file and rebuild the kernel:
 - # /usr/sbin/doconfig

Note	

Do not specify the -c option to doconfig. If you do, doconfig will use the existing kernel configuration file which will not have the appropriate controller entry for the new graphics card.

- 5. Save the old /vmunix file and move the new kernel to /vmunix.
- 6. Shut down the system:
 - # /usr/sbin/shutdown -h now
- 7. Boot the new kernel:

>>> boot

If you remove this patch from your system after you have rebuilt the kernel to incorporate support for the new Ethernet card as described previously, you will need to rebuild the kernel. To do this, follow the steps given previously. The doconfig running on the original, unpatched genvmunix will not recognize the new Ethernet driver.

1.6.6 Intelligent I/O Disks with mnemonic ri

If Patch 640.00 is installed on a system with Intelligent I/O (I2O) disks that use the device identifier, mnemonic ri, Patch 571.00 should also be installed if the user uses the diskconfig utility. Without Patch 571.00, the diskconfig utility will not recognize or configure the Intelligent I/O (I2O) disks.

1.6.7 Virtual Memory Problem

Installing Patch 640.00 on a system running Tru64 UNIX 4.0D through 4.0F may cause the system to crash if you run an application that maps a large number of file system objects into virtual memory using the mmap(2) function call. This problem may occur with large threaded applications, such as the Netscape Enterprise Web Server, which use this technique to improve performance and scalibility.

To avoid this problem, disable the kernel's virtual memory (vm:) subsystem attribute vm-map-index-enable after installing the patch and before rebooting the system. The attribute is disabled when its value is set to zero at boot time.

Enter the following commands at the shell prompt (when logged in as root) to add or modify the vm-map-index-enable attribute entry in the /etc/sysconfigtab file:

```
$ su root
$ cat << _EOF_ > /tmp/vm.stanza
> vm:
> vm-map-index-enabled=0
> _EOF_
$ sysconfigdb -m -f /tmp/vm.stanza vm
$rm -f /tmp/vm.stanza
$ reboot.
```

See the sysconfigdb(8) man page for additional information.

This problem will be fixed in the next release of the patch kits.

1.6.8 PCI To Ethernet/Graphics Combo Adapter

This patch provides support for the PCI To Ethernet/Graphics Combo Adapter (3X-DEPVD-AA). If you have a system with this adapter, you will need to reconfigure and rebuild the kernel after installing this patch. To do this:

- 1. Shut down the system:
 - # /usr/sbin/shutdown -h now
- Boot genvmunix to single-user mode:
 - >>> boot -fi genvmunix -fl s
- After the system boots to single-user mode, mount the file systems, run the update command, and activate the swap partition:
 - # /sbin/bcheckrc
 - # /sbin/update
 - # /sbin/swapon -a
- Run doconfig to create a new kernel configuration file and rebuild the kernel:
 - # /usr/sbin/doconfig

Note	
14016	

Do not specify the -c option to doconfig. If you do, doconfig will use the existing kernel configuration file, which will not have the appropriate controller entry for the PCI To Ethernet/Graphics Combo Adapter.

- Save the old /vmunix file and move the new kernel to /vmunix.
- Shut down the system:
 - # /usr/sbin/shutdown -h now
- 7. Boot the new kernel:
 - >>> boot

If you remove this patch from your system after you have rebuilt the kernel, to incorporate support for the PCI To Ethernet/Graphics Combo Adapter as previously described, you will need to rebuild the kernel again to restore generic VGA graphics support. To do this, follow the steps previously given.

If doconfig is running on the original kernel, the unpatched genymunix will not recognize the PCI To Ethernet/Graphics Combo Adapter and will include generic VGA graphics support in the resulting kernel.

1.6.9 Pleiades II Switches

To determine if target IDs are being consumed by the switch, look at the contents of the /etc/emx.info file. If a FC Port Name exists that does not start with 0x0050 (a HSG80) or a 0x0010 (a KGPSA), it is most likely a switch entry consuming the target ID (or an unsupported FC device exists on the fabric).

To remove the switch entry from the emx target ID mappings, in addition to installing this patch, the /sys/data/emx data.c file must be modified to contain the switch entry to be deleted (by setting the target ID to -1). See the reference pages for emx and emx_data.c for instructions on modifying the emx_data.c file.

After the emx_data.c file has been modified, the kernel must be regenerated and the resulting kernel booted.

1.6.10 I/O Throttling/Smooth Sync

Note		
Smooth Sync is for UNIX File System (UFS) only.		
Note		
To activate I/O Throttling/Smooth Sync, you must install Patch 299.00.		

The new mount options are smsync2 and throttle. The smsync2 option enables an alternate smsync policy in which dirty pages do not get flushed until they have been dirty and idle for the smoothsync age period (the default 30 is seconds). The default policy is to flush dirty pages after being dirty for the smoothsync age period, regardless of continued modifications to the page. Note that mmaped pages always use this default policy, regardless of the smsync2 setting.

For example, change the /etc/fstab entries from:

```
/dev/rz12e /mnt/test ufs rw 0 2

to:
/dev/rz12e /mnt/test ufs rw,smsync2,throttle 0 2

______ Note
_____ Note
_____ If you choose not to use smsync2 (which does not affect mmaped buffers),
```

just remove the smsync2 option from the previous string.

Append any tuning changes to /etc/sysconfigtab. See the TUNING notes that follow for a description of the new io-throttle-shift and io-throttle-maxmzthruput tunables. These tunables are configured in the vfs stanza. The following three lines make up an example:

```
vfs:
io-throttle-shift = 1
io-throttle-maxmzthruput = 1
```

When removing this patch, follow these steps:

- 1. Remove the lines added above to /etc/inittab.
- 2. Remove any additions to /etc/fstab you may have made (see previous instructions).

Failure to remove /etc/inittab and /etc/fstab modifications may result in unknown attribute messages, particularly upon system reboot.

TUNING

The purpose of this patch is to minimize system stalls resulting from a heavy system I/O load. This patch introduces a smoothsync approach to writing delayed I/O requests and introduces I/O throttling.

Using smoothsync allows each dirty page to age for a specified time period before getting pushed to disk. This allows more opportunity for frequently modified pages

to be found in the cache, which decreases the net I/O load. Also, as pages are enqueued to a device after having aged sufficiently, as opposed to getting flushed by the update daemon, spikes are minimized in which large numbers of dirty pages are locked on the device queue.

I/O throttling further addresses the concern of locking dirty pages on the device queue. It enforces a limit on the number of delayed I/O requests allowed to be on the device queue at any point in time. This allows the system to be more responsive to any synchronous requests added to the device queue, such as a read or the loading of a new program into memory. This may decrease the duration of process stalls for specific dirty buffers, as pages remain available until placed on the device queue.

The relevant tunable variables are:

```
smoothsync-age
```

This variable can be adjusted from 0 (off) up to 300. This is the number of seconds a page ages before becoming eligible for being flushed to disk via the smoothsync mechanism. A value of 30 corresponds to the "guarantee" provided by the traditional UNIX update mechanism. Increasing this value increases the exposure of lost data should the system crash, but can decrease net I/O load (to improve performance) by allowing the dirty data to remain in cache longer. In some environments, any data that is not up to date is useless; these are prime candidates for an increased smoothsync-age value. The default value of smoothsync-age is 30.

io-throttle-shift

The greater the number of requests on an I/O device queue, the longer the time required to process those requests and make those pages and device available. The number of concurrent delayed I/O requests on an I/O device queue can be throttled by setting the io-throttle-shift tunable. The throttle value is based on this tunable and the calculated I/O completion rate. The throttle value is proportional to the time required to process the I/O device queue. The correspondences between io-throttle-shift values and the time to process the device queue are:

io-throttle-shift time to process device queue (sec)

-2	0.25	
-1	0.5	
0	1	
1	2	
2	4	

For example, an io-throttle-shift value of 0 corresponds to accommodating 1 second of I/O requests. The valid range for this tunable is [-4..4] (not all values are shown in the previous table; you can extrapolate). The default value of io-throttle-shift is 1. Environments particularly sensitive to delays in accessing the I/O device might consider reducing the io-throttle-shift value.

io-maxmzthruput

This is a toggle that trades off maximizing I/O throughput against maximizing the availability of dirty pages. Maximizing I/O throughput works more aggressively to keep the device busy, but within the constraints of the throttle. Maximizing the availability of dirty pages is more aggressive at decreasing stall time experienced when waiting for dirty pages.

The environment in which you might consider setting io-maxmzthruput off (0) is one in which I/O is confined to a small number of I/O-intensive applications, such that access to a specific set of pages becomes more important for overall performance than does keeping the I/O device busy. The default value of io-maxmzthruput is 1. Environments particularly sensitive to delays in accessing sets of frequently used dirty pages might consider setting io-maxmzthruput to 0.

1.6.11 Granularity Hint Regions Restriction Removal

This patch removes a Granularity Hint Regions (also called GH chunks) restriction which may be encountered on AlphaServerTM™ DS20 and ES40 systems running the Tru64 UNIX Version 4.0F release. This restriction can reduce performance for certain database applications.

The following error message on the system's console terminal (also logged in /var/adm/messages) indicates possible performance loss for applications using GH chunks:

```
gh chunks value of # invalid
```

where # is a number that varies depending on memory size.

To remove the GH chunks restriction, you need to modify your target kernel configuration file (and rebuild the kernel) and change the state of a console firmware environment variable. To make these changes, follow these steps:

1. Follow the steps in Section 4.5.3 of the *Guide to System Adminstration*, with the following exceptions:

In step 4, edit the configuration file and add the following line immediately before the first line starting with makeoptions:

```
makeoptions LOADADDR="fffffc0000430000"
```

In step 6, instead of /usr/sbin/shutdown -r now, add the following line:

```
/usr/sbin/shutdown -h now
```

2. Check the console firmware version:

```
P00>>>show version
```

If the version is not V5.5 or later, you need to upgrade your firmware to V5.5 or later.

3. Change the value of the console_memory_allocation environment variable from old to new and reset the system:

```
P00>>>set console_memory_allocation new P00>>>init
```

4. Boot the new kernel:

```
P00>>>boot
```

If the new kernel fails to boot use one of the following procedures:

```
P00>>>set console_memory_allocation old
P00>>>init
P00>>>boot -fi vmunix.save
or:
P00>>>boot -fi genvmunix
```

Correct the error and repeat the previous procedure.

Additional Information

• If you encounter the following error message, you have most likely attempted to boot a kernel with the old load address:

```
Bootstrap address collision, image loading aborted To boot old kernels:

P00>>>set console_memory_allocation old

P00>>>init
```

Note
The generic kernel (/genvmunix) will boot with console_memory_allocation set to old or new.

 The patch kit installs a new /usr/sbin/sizer command. If you rebuild the kernel using Section 4.5.1 or 4.5.2 of the System Administration Manual, the new sizer will automatically adjust the kernel's load address.

If you customized your existing configuration file, doconfig allows you to edit the new configuration file so you can restore your customizations.

1.7 Release Note for DEC 7000 Upgrades to AlphaServer 8400

This release note concerns systems that were upgraded from DEC 7000 to AlphaServer 8400 that have not installed the DWLPA-AA, DWLPB-AA, or the KFTIA. These are the I/O enhancements for the AlphaServer 8400.

Add the following information to the /sys/conf/SYSTEMNAME file:

```
bus
          tiop0
                  at tlsb0
                            vector
                                    tioperror
          pci0
                  at tiop0
                            slot 0
bus
callout after_c "../bin/mkdata pci"
          isp0
                 at pci0 slot 0 vector ispintr
bus
controller
           scsi0
                  at isp0
                              slot 0
```

You must do this on every reconfiguration of the system.

1.8 Release Notes for Tru64 UNIX Patches 476.00 and 351.00

The following release notes provide Visual Threads Upgrade information and updated information for the quotacheck(8), fsck(8), and fstab(4) reference pages.

1.8.1 Visual Threads Upgrade Required

Visual Threads users will need to upgrade to the latest version of Visual Threads for the race detection rules to work. The Visual Threads upgrade is available from http://www.tru64unix.compaq.com/visualthreads and will be available in the next Developers' Tooklit Supplement.

1.8.2 quotacheck(8), fsck(8), and fstab(4) Reference Pages

quotacheck(8) Reference Page Update

```
SYNOPSIS

/usr/sbin/quotacheck [-guv] filesystem ...

OLD> /usr/sbin/quotacheck -a [-guv] [-l number]

NEW> /usr/sbin/quotacheck -a [-guv] [-l number] [-t [no]type]

FLAGS

OLD> -a Checks all file systems identified in the /etc/fstab file as read/write with disk quotas.
```

- NEW> -a Checks all UFS and AdvFS file systems identified in the /etc/fstab file as read/write with userquota and/or groupquota options specified, and a pass number of 1 or greater. If the -t option is specified, only the file systems of the specified type will be checked. Alternatively, if type is prefixed with 'no', then the valid file systems in the /etc/fstab file that do not have that type will be checked.
- OLD> -l number Specifies the number of times to perform disk quota
- NEW> -l number Specifies the maximum number of parallel quotacheck processes to run at one time.
- NEW> -t [no]type
- Specifies the file system type. The supported file systems are NEW>

advfs - Advanced File System (AdvFS)

ufs - UNIX File System (UFS)

See fstab(4) for a description of file system types. If the 'no' prefix is used, all of the above file types except the one specified are checked.

Note, the -t flag is only valid when used with the -a flag.

DESCRIPTION

- OLD> The quotacheck command examines each specified file system, builds a table of current disk usage, and compares this table against that stored in the disk quota file for the file system. If any inconsistencies are detected, both the quota file and the current system copy of the incorrect quotas are updated. Each file system must be mounted with quotas enabled.
- NEW> The quotacheck command examines each specified file system, builds a table of current disk usage, and compares this table against that stored in the disk quota file for the file system. If any inconsistencies are detected, both the quota file and the current system copy of the incorrect quotas are updated.
- OLD> The quotacheck command runs parallel passes on file systems using the number specified in the fsck field of the file system's entry in the /etc/fstab file. The quotacheck command only checks file systems with pass number 1 or higher in the fsck field. A file system with no pass number is not checked.
- NEW> The quotacheck -a command runs parallel passes on file systems using the number specified in the /etc/fstab pass number field. The quotacheck command only checks file systems with pass number 1 or higher in the fsck field. A file system with no pass number is not checked.
- OLD> For both UFS file systems and AdvFS filesets, you should assign the root file system a fsck field value of 1, and a value of 2 or higher to other file systems. See fstab(4) for more information.
- NEW> For both UFS file systems and AdvFS filesets, you should assign the root file system a pass number of 1, and a value of 2 or higher to other file systems. See fstab(4) for more information.
- OLD> The quotacheck command checks only file systems that have the userquota or groupquota option specified in the /etc/fstab file.
- NEW> The quotacheck command checks only file systems that are mounted. UFS file systems must also have userquota and/or groupquota options specified in the /etc/fstab file. The userquota and groupquota

options are only needed for AdvFS file systems if quotas are actually going to be enforced or if they are to be selected with the -a option.

fsck(8) Reference Page Update

OLD> When the system boots, the fsck program is automatically run with the -p flag. The program reads the /etc/fstab file to determine which file systems to check. Only partitions that are specified in the fstab file as being mounted "rw" or "ro" and that have a non-zero pass number are checked. File systems that have a pass number 1 (usually only the root file system) are checked one at a time. When pass 1 completes, all the remaining file systems are checked, with one process running per disk drive.

NEW> When the system boots, the fsck program is automatically run with the -p flag. The program reads the /etc/fstab file to determine which file systems to check. Only partitions that are specified in the fstab file as being mounted "rw" or "ro" and that have a non-zero pass number are checked. File systems that have a pass number 1 (usually only the root file system) are checked one at a time. When pass 1 completes, the remaining pass numbers are processed with one parallel fsck process running per disk drive in the same pass.

NEW> The per disk drive logic is based on the /dev/disk/dsk0a syntax where different partition letters are treated as being on the samedisk drive. Partitions layered on top of an LSM device may not follow this naming convention. In this case unique pass numbers in /etc/fstab may be used to sequence fsck checks.

fstab(4) Reference Page Update

userquota [=filename] and groupquota [=filename]

If quotas are to be enforced for users or groups, one or both of the options must be specified. If userquota is specified, user quotas are to be enforced. If groupquota is specified, group:

OLD> quotas are to be enforced.

NEW> quotas are to be enforced (also see quotaon and quotaoff(8)).

OLD> For UFS file systems, the sixth field (fsck) is used by the fsck command to determine the order in which file system checks are done at reboot time. For the root file system, specify 1 in the fsck field. For other UFS file systems, specify 2 or higher in the fsck field. Each UFS file system should have a unique fsck value.

NEW> For UFS file systems, the sixth field (pass number) is used by the fsck and quotacheck commands to determine the order in which file system checks are done at reboot time. For the root file system, specify 1 in the fsck field. For other UFS file systems specify 2 or higher in the pass number field.

OLD> For AdvFS filesets, the sixth field is a pass number field that allows the quotacheck command to perform all of the consistency checks needed for the fileset. For the root file system, specify 1 in the fsck field. Each AdvFS fileset in an AdvFS file domain should have a unique fsck value, which should be 2 or higher.

NEW> For AdvFS filesets, the sixth field is a pass number field that allows the quotacheck command to perform all of the consistency checks needed for the fileset. For the root file

system, specify 1 in the fsck field. For other AdvFS file systems specify 2 or higher in the pass number field.

OLD> File systems that are on the same disk are checked sequentially, but file systems on different disks are checked at the same time to utilize parallelism available in the hardware. If the sixth field is not present or zero, a value of 0 is returned and the fsck command assumes that the file system does not need to be checked.

NEW> File systems that are on the same disk or domain are checked sequentially, but file systems on different disks or domains but with the same or greater than 1 pass number are checked at the same time to utilize parallelism available in the hardware. When all the file systems in a pass have completed their checks, then the file systems with the numerically next higher pass number will be processed.

NEW> The UFS per disk drive logic is based on the /dev/disk/dsk0a syntax where different partition letters are treated as being on the same disk drive. Partitions layered on top of an LSM device may not follow this naming convention. In this case unique pass numbers may be used to sequence fsck and quotacheck processing. If the sixth field is not present or zero, a value of 0 is returned and the fsck command assumes that the file system does not need to be checked.

1.9 Release Note for Patch 315.00

This is a release note for the Enhanced Round Robin Sequential Read Patch.

If the system configurable parameter lsm:lsm_V_ROUND_enhanced is set (value = 1) the enhanced read round robin policy is activated. This new policy stores the last block accessed by the previous I/O request. When returning for another block in round robin (V_ROUND) mode, that value is compared to the current read. If it is within a predefined, user-configurable value (lsm:lsm_V_ROUND_enhance_proximity), then the same plex is used. Otherwise the next plex is used as for a normal round robin behavior.

The two new additional tunable parameters are 1sm V ROUND enhanced set to 1 by default (V ROUND read is activated) and 1sm V ROUND enhance proximity is set to 512 by default.

Append any tuning changes to/etc/sysconfigtab. See the TUNING notes below for a description of the new lsm_V_ROUND_enhanced and lsm_V_ROUND_enhance_proximity tunables. These tunables are configured in the 1sm stanza. For example:

Lsm:
lsm_V_ROUND_enhanced = 1
lsm_V_ROUND_enhance_proximity = 1024
Note
If you already have an lsm stanza in your sysconfigtab file, add the two lsm_V_ROUND entries.

TUNING

The purpose of this patch is to increase performance with sequential reads. This patch introduces a new enhanced round robin mode where the last block read is now compared to the next block to read and a check is added

to see if last block number-next block number is less than or equal to <code>lsm_V_ROUND_enhance_proximity</code>. If it is, read from the same plex. This is to attempt to hit the disk cache, and so increase performance.

The relevant tunable variables are as follows:

1sm V ROUND enhanced

This variable activates the new enhanced round robin read policy if it is set to TRUE (1). Otherwise the policy is deactivated.

DEFAULT = 1

lsm_V_ROUND_proxmity

This variable provides the proximity in which the last read and new read most lie in an attempt to read data from the disk's cache by reading from the same plex. The variable can be adjusted from 0 to 4096.

DEFAULT = 512

1.10 Release Note for Patch 351.00

For more information about the functionality provided and special installation instructions related to this patch, please refer to the online README file located at:

http://www.service.digital.com/patches/

From this URL directory, click on the following link:

duv40fwlseco2.README

Note	
	Note

It may be necessary to navigate additional directories below this top level URL to find the specific ${\tt README}$ file related to this patch.

1.11 Release Notes for Tru64 UNIX Patch 713.00

This patch provides the X server support for the new 3Dlabs Oxygen VX1 PCI graphics card. In order to obtain full support for this graphic card, you must also select Patch 640.00, which is the driver portion of the patch.

A list of supported platforms is available on the following web page:

http://www.compag.com/alphaserver/products/options.html

1.12 Release Note for Tru64 UNIX Patch 592.00

This patch contains a solution for the following issue:

Compaq has advised owners of DS10, DS10L, ES40 AlphaServers, and XP900 AlphaStations that Compaq has determined in laboratory testing that there is a theoretical possibility that during read and write operations to the floppy disk on these systems, a single byte of data may be inaccurately read or written without notice to the user or system. The potential for this anomaly exists only if floppy disk read or write operations are attempted while there is extremely heavy traffic on these Alpha systems' internal input/output busses.

Although Compaq has observed the anomaly only in laboratory tests designed to create atypical system stresses, including almost constant use of the floppy disk drive, Compaq has informed owners of the remote possibility that the anomaly could occur so that they may take precautions to prevent it.

Compaq recommends that the solution be installed by all DS10, DS10L, ES40 AlphaServers, and XP900 AlphaStation customers.

The solution to this issue is also available as an individual, manually installed patch kit named floppy_CSP_v40g.tar.gz, available from:

http://ftpl.support.compaq.com/public/unix/v4.0g

1.13 Release Note for TruCluster DRD Workaround

Adding a new member to an existing cluster will fail under the following conditions:

- The cluster is configured with a large number of DRDs.
- You are performing a rolling upgrade from TruCluster V1.5 to V1.6.
- The ASE data base has not been updated to the V1.6 structure.

To work around this problem, you must update the data base using the Enable ASE V1.6 functionality option from the Managing the ASE menu on the existing member prior to attempting to add the new member. Thus, the new member will be added with a V1.6-type ASE data base and will proceed successfully.

A patch will be in released in the near future.

Summary of Base Operating System Patches

This chapter summarizes the base operating system patches included in Patch Kit-0006.

Table 2–1 lists patches that have been updated.

Table 2–2 provides a summary of patches.

Table 2-1: Updated Base Operating System Patches

Patch IDs	Change Summary
Patches 646.00, 668.00, 672.00, 676.00, 678.00, 686.00, 703.00, 705.00, 707.00, 711.00, 718.00, 725.00, 727.00, 733.00, 735.00, 737.00, 739.00,	New
Patches 139.00, 97.00, 140.00, 39.00, 165.00, 228.00, 301.00, 590.00, 34.00, 9.00, 10.00, 13.00, 27.00, 30.00, 55.00, 96.00, 99.00, 102.00, 106.00, 107.00, 110.00, 116.00, 117.00, 122.00, 126.00, 129.00, 141.00, 146.00, 160.00, 164.00, 174.00, 31.00, 178.00, 81.00, 112.00, 134.00, 224.00, 230.00, 238.00, 239.00, 244.00, 248.00, 255.00, 257.00, 259.00, 265.00, 270.00, 291.00, 294.00, 303.00, 307.00, 310.00, 312.00, 317.00, 118.00, 33.00, 49.00, 50.00, 51.00, 52.00, 88.00, 100.00, 115.00, 121.00, 54.00, 161.00, 331.00, 227.00, 234.00, 258.00, 261.00, 264.00, 280.00, 292.00, 300.00, 321.00, 176.00, 329.00, 229.00, 83.00, 246.00, 131.00, 73.00, 58.00, 180.00, 210.00, 288.00, 304.00, 320.00, 326.00, 160.0, 130.00, 332.00, 152.00, 263.00, 92.00, 149.00, 150.00, 181.00, 250.00, 278.00, 305.00, 86.00, 324.00, 132.00, 360.00, 362.00, 365.00, 366.00, 368.00, 369.00, 370.00, 371.00, 372.00, 375.00, 377.00, 379.00, 380.00, 382.00, 388.00, 389.00, 391.00, 392.00, 393.00, 397.00, 398.00, 399.00, 403.00, 424.00, 411.00, 412.00, 413.00, 414.00, 418.00, 423.00, 424.00, 425.00, 426.00, 429.00, 430.00, 432.00, 433.00, 444.00, 425.00, 426.00, 445.00, 445.00, 445.00, 445.00, 445.00, 445.00, 445.00, 448.00, 450.00, 480.00, 680.00, 680.00, 680.00, 680.00, 680.00, 680.00, 680.00, 680.00, 680.00, 680.00, 680.00, 680.00, 680.00, 6	Patch 640.00
Patch 361.00	Patch 642.00
Patches 35.00, 240.00, 384.00	Patch 644.00
Patches 79.00, 125.00, 138.00, 172.00, 91.00, 177.00, 173.00, 247.00, 266.00, 408.00, 48.00, 438.00, 87.00, 457.00, 508.00, 509.00, 511.00, 647.00, 648.00, 649.00	Patch 651.00
Patches 428.00, 431.00, 517.00	Patch 653.00
Patches 15.00, 23.00, 24.00, 25.00, 120.00, 142.00, 145.00, 156.00, 175.00, 376.00, 410.00, 440.00, 521.00, 654.00, 655.00, 656.00, 657.00	Patch 659.00

Table 2–1: Updated Base Operating System Patches (cont.)

Patches 17.00, 383.00, 534.00	Patch 661.00
Patches 128.00, 293.00, 309.00, 522.00, 524.00, 662.00	Patch 664.00
Patches 275.00, 289.00, 386.00, 538.00, 540.00	Patch 666.00
Patches 94.00, 451.00	Patch 670.00
Patches 42.00, 276.00, 452.00, 167.00, 588.00	Patch 674.00
Patch 124.00	Patch 680.00
Patch 204.00	Patch 682.00
Patches 22.00, 427.00	Patch 684.00
Patches 78.00, 439.00	Patch 688.00
Patch 186.00	Patch 690.00
Patches 113.00, 207.00, 208.00, 249.00, 401.00, 580.00, 582.00, 691.00, 692.00, 693.00	Patch 695.00
Patch 119.00	Patch 697.00
Patch 159.00	Patch 699.00
Patches 47.00, 387.00	Patch 701.00
Patches 64.00, 74.00, 199.00, 200.00, 220.00, 352.00, 359.00	Patch 709.00
Patch 577.00	Patch 713.00
Patches 56.00, 95.00, 103.00, 151.00, 274.00, 436.00, 714.00	Patch 716.00
Patche 213.00	Patch 720.00
Patches 378.00, 721.00	Patch 723.00
Patch 357.00	Patch 729.00
Patch 43.00	Patch 731.00
Patches 279.00, 319.00	Patch 741.00
Patches 236.00, 742.00	Patch 744.00
Patches 158.00, 253.00, 282.00, 285.00	Patch 746.00

Table 2–2: Summary of Base Operating System Patches

Patch IDs	Abstract
Patch 3.00	Patch: Security (SSRT0585U)
OSF440CDE-003	State: Existing
	A potential security vulnerability has been discovered where, under certain circumstances, system integrity may be compromised. This may be in the form of improper file or privilege management. Compaq has corrected this potential vulnerability.
Patch 7.00	Patch: dxcalendar Reminder Displays Through dxpause Screen
OSF440DX-001	State: Existing
	This patch fixes the problem where the dxcalendar reminder displays through the pause screen (dxpause) and remains on the top of the pause window.

Table 2-2: Sum	nmary of Base Operating System Patches (cont.)
Patch 8.00 OSF440-010	Patch: Fix For POP Mail Handler State: Existing This patch corrects the following:
	 Netscape Mail clients are unable to access their mailboxes after an initial session. The /usr/spool/pop/username.lock file is left over and must be removed manually.
	 The POP mail handler fails to properly rename its temp file after receiving a quit command.
Patch 11.00 OSF440-013	Patch: Security (SSRT0596U) State: Existing
	A potential security vulnerability has been discovered where, under certain circumstances, system integrity may be compromised. This may be in the form of improper file or privilege management. Compaq has corrected this potential vulnerability.
Patch 19.00	Patch: Fix For yacc
OSF440-020	State: Existing
	This patch fixes a problem in yacc that causes it to generate parse tables that result in the parser not executing a user-specified error recovery action. If a yacc specification worked in Version 3.2 and no longer works in Version 4.0, this may be the problem.
Patch 20.00	Patch: Cannot Use ipcs Cmd On System Not Booted With vmunix
OSF440-022	State: Existing
	This patch corrects a problem that prevents a user from using the ipcs command on a system whose kernel has been booted from a file that is not /vmunix.
Patch 21.00	Patch: Fix For XTI And DECnet/OSI
OSF440-023A	State: Supersedes patch OSF440-016A (14.00) This patch corrects the following:
	 Fixes a problem in which an application using the X/Open Transport Interface (XTI) and the DECnet/OSI transport provider is unable to disconnect a rejected request.
	 Fixes a streams problem in libxti. The t_getprotaddr() function will cause a memory core dump if either of its second or third argument is NULL.
Patch 28.00	Patch: Security (SSRT0556U)
OSF440-030	State: Existing
	A potential security vulnerability has been discovered where, under certain circumstances, users may gain unauthorized access. Compaq has corrected this potential vulnerability.
Patch 32.00	Patch: mkdir -p Not Returning Error
OSF440-034	State: Existing This patch fixes a problem with the mkdir -p command. mkdir -p would not return an error if the last component in the pathname already exists.
Patch 36.00	Patch: volrootmir -a Cmd Fails
OSF440-041	State: Existing
	This patch fixes a problem where the LSM command volrootmir -a fails if the source and target disks are not the same type.
Patch 37.00	Patch: volrecover Not Returning Failed Status Code
OSF440-042	State: Existing This patch corrects a problem in which a failure of the volrecover utility will not return a failed status code.
·	

Patch 38.00	Patch: quotaon Returns Incorrect Error Status	
OSF440-043	State: Existing This patch fixes a problem in which the quotaon command returned an incorrect error status if the file system did not exist.	
Patch 40.00	Patch: binmail Delivers Only Partial Messages	
OSF440-046	State: Existing This patch fixes binmail to prevent partial delivery of mail messages when disk quota is reached.	
Patch 41.00	Patch: Fix For nroff Y2K Problem	
OSF440-047A	State: Existing This patch fixes a Y2K problem with the nroff text formatter in which the years after 1999 are translated to be 19xxx with xxx being the number of years that have passed since 1900. In this case, the year 2010 displays as 19110.	
Patch 46.00 OSF440-052A	Patch: Shared Library Fix For curses-based Applications State: Existing	
051 110 002.1	The keymap used with curses functionality was not in sync with the table contained in the term.h header file. This change corrects that and enables several nonfunctioning keys in curses-based applications.	
Patch 60.00 OSF440-008	Patch: Fix For spo_misc_errors errlog Entries	
	State: Existing This patch fixes the cause of the spurious spo_misc_errors errlog entron 4100 class systems.	
Patch 61.00 OSF440X11-001	Patch: Enhancement For makedepend Utility State: Existing	
	This patch increases the maximum number of files that one file can depend on in the makedepend utility from 1024 to 4096.	
Patch 66.00 OSF440-023B	Patch: libxti/libtli Static Library Fix State: Supersedes patch OSF440-016B (65.00)	
	This patch corrects the following:	
	 Fixes a problem in which an application using the X/Open Transport Interface (XTI) and the DECnet/OSI transport provide is unable to disconnect a rejected request. 	
	 Fixes a streams problem in libxti. The t_getprotaddr() function will cause a memory core dump if either of its second or third argument is NULL. 	
Patch 67.00	Patch: mount Cmd Sometimes Kills Other Processes	
OSF440-033B	State: Existing This patch fixes a problem with the mount command where it sometimes kills other processes.	
Patch 68.00 OSF440-047B	Patch: nroff Incorrectly Translates Years After 1999 State: Existing	
	This patch fixes a Y2K problem with the nroff text formatter in whice the years after 1999 are translated to be 19xxx with xxx being the number of years that have passed since 1900. In this case, the year 2010 displays as 19110.	
Patch 69.00 OSF440-052B	Patch: Static Library Fix For curses-based Applications State: Existing	
ODI 110 006D	The keymap used with curses functionality was not in sync with the	

table contained in the term.h header file. This change corrects that and enables several nonfunctioning keys in curses-based applications.

Table 2–2: Summary of Base Operating System Patches (cont.)			
Patch 75.00 OSF440-060B	Patch: chvol Read and Write Transfer Size Increased State: Existing This patch corrects the following:		
	AdvFS volumes were not setting the default I/O byte transfer size to the preferred size reported by the disk drives.		
	AdvFS chvol read and write transfer size range was increased.		
	• The read-ahead algorithm was modified to improve performance under certain conditions.		
Patch 76.00	Patch: Fix for simple lock panic		
OSF440-001	State: Existing This patch fixes a system panic with the following panic string:		
	simple_lock: time limit exceeded		
Patch 80.00 OSF440-103	Patch: Fix for cdfs file system State: Existing This patch fixes a problem with the cdfs file system. The default a		
	partitions are being made incorrectly by the disk driver for ISO-9660 CDs causing data corruption when reading beyond the end of a partition. Only new and non-Compaq CD-ROM drives are affected.		
Patch 82.00	Patch: Fix for system crash		
OSF440-106	State: Existing This patch fixes a problem in which the system was consistently crashing by pressing keys during the transition from firmware callback to OS console handling.		
Patch 93.00	Patch: Fix for kdbx		
OSF440-117	State: Supersedes patch OSF440-104B (201.00) This patch corrects the following:		
	• Fixes a problem with kdbx. A core file created by kdbx was left in the root directory when recovering from a system crash.		
	 Fixes a problem with kdbx. The trace command was showing all threads of a process when using the option that should show only selected threads. 		
Patch 101.00 OSF440-126	Patch: Fix for prof -pixie -asm command State: Supersedes patch OSF440-122B (202.00) This patch corrects the following:		
	• Fixes the name demangling for the tools that print symbol table names generated by the C++ V6.2 compiler. This problem will only occur for most C++ objects compiled with the ANSI options.		
	 Fixes a problem where prof -pixie -asm would dump core if the executable being profiled contains extremely long symbol names. 		
Patch 104.00	Patch: System hang prevents rlogins or telnets		
OSF440-130	State: Existing This patch fixes a problem where systems could hang in the audit code, preventing rlogins or telnets into it.		
Patch 105.00	Patch: Fix for class_admin class_daemon problem		
OSF440-131A	State: Existing This patch fixes a class_admin/class_daemon problem. When a PID is added to a class it cannot be removed from the class scheduler until the process terminates or the class_scheduler has been stopped.		

Patch 127.00 OSF440-153	Patch: Security (SSRT0583Z) State: Existing
	A potential security vulnerability has been discovered where, under certain circumstances, system integrity may be compromised. This may be in the form of improper file or privilege management. Compaq has corrected this potential vulnerability.
Patch 135.00 OSF440-021	Patch: Fix for ar command State: Existing This patch eliminates the previous limitation on the maximum number of external symbols that could be handled by the ar command.
Patch 144.00 OSF440-064	 Patch: Fix for NFS problems State: Existing This patch corrects the following: When starting or stopping NFS, NFS was not checking for NFS daemons running. rpc.pcnfsd was causing core dumps when receiving a SIGTERM signal.
Patch 148.00 OSF440-069	Patch: Fix for rsh hang State: Existing This patch fixes rsh(1) hanging forever in select().
Patch 153.00 OSF440-074	Patch: Fixes a problem within the SCSI and tape subsystems State: Existing This patch fixes a problem within the SCSI and tape subsystems, in which an expression was not being evaluated properly.
Patch 162.00 OSF440-083	Patch: Fix for unresolved symbol:scc_configure message State: Existing This patch fixes a problem in which systems that use Compaq Tru64 UNIX and install DECnet/OSI and WDD would get the following error message when attempting to build a kernel: unresolved symbol:scc_configure
Patch 169.00 OSF440-090	Patch: Fix for crontab -e user command State: Existing This patch fixes a problem with crontab in which, when root runs crontab -e user, the user's crontab file is edited and saved, but is not re-read by the cron daemon. Instead, root's crontab file is re-read.
Patch 170.00 OSF440-091	Patch: Fixes a problem with the stdhosts command State: Existing This patch fixes a problem with the stdhosts command when the file processed has lines longer than 256 characters. The error message "tdhost:malformed line ignored" is displayed.
Patch 179.00 OSF440-192	 Patch: Fix for panics on AlphaServer GS140/GS60 systems State: Supersedes patch OSF440-002 (18.00) This patch corrects the following: Resolves corrupt EV6 binary error log entries for IOP detected UDE (Uncorrectable Data Error) packets on AlphaServer 8200/8400 platforms. Fixes a problem on some AlphaServer GS140/GS60 configurations where a simple lock timeout or TB shoot ack timeout panic may occur.

Patch 182.00	Patch: Fix for X server color map problem
OSF440CDE-010	State: Existing
	This patch fixes a problem where there were no available colors in the X server's color map after the CDE screen lock was displayed.
Patch 183.00	Patch: Security (SSRT0614U)
OSF440CDE-011	State: Existing
	A potential security vulnerability has been discovered where, under certain circumstances, system integrity may be compromised. This may be in the form of improper file or privilege management. Compaq has corrected this potential vulnerability.
Patch 188.00	Patch: Compaq SCSI SNMP sub-agent returns incorrect info
OSF440DX-003	State: Existing This patch fixes a problem that causes the Compaq SCSI SNMP
	subagent (cpq_mibs) to often return incorrect SCSI CD-ROM and tape devices model information, which results in invalid information displaying on the Insight Management web pages.
Patch 194.00	Patch: Security (SSRT0612U)
OSF440DX-009	State: Existing
	A potential security vulnerability has been discovered where, under certain circumstances, system integrity may be compromised. This may be in the form of improper file or privilege management. Compaq has corrected this potential vulnerability.
Patch 196.00	Patch: XDMCP Indirect queries do not work
OSF440X11-006	State: Existing
	This patch fixes a problem in the X Display Manager (xdm) where XDMCP Indirect queries do not work.
Patch 198.00	Patch: X server crashes when viewing TIFF images
OSF440X11-008	State: Existing
	This patch fixes a problem where viewing certain TIFF images with an image viewer crashed the X server.
Patch 205.00	Patch: Fix for dxaccounts BadPixmap error
OCEAAOCDE OOOD	State: Existing
OSF440CDE-009B	State: Existing This patch fixes a problem where the Account Manager application,

	certain circumstances, system integrity may be compromised. This may be in the form of improper file or privilege management. Compaq has corrected this potential vulnerability.
Patch 188.00	Patch: Compaq SCSI SNMP sub-agent returns incorrect info
OSF440DX-003	State: Existing
	This patch fixes a problem that causes the Compaq SCSI SNMP subagent (cpq_mibs) to often return incorrect SCSI CD-ROM and tape devices model information, which results in invalid information displaying on the Insight Management web pages.
Patch 194.00	Patch: Security (SSRT0612U)
OSF440DX-009	State: Existing
	A potential security vulnerability has been discovered where, under certain circumstances, system integrity may be compromised. This may be in the form of improper file or privilege management. Compaq has corrected this potential vulnerability.
Patch 196.00	Patch: XDMCP Indirect queries do not work
OSF440X11-006	State: Existing
	This patch fixes a problem in the X Display Manager (xdm) where XDMCP Indirect queries do not work.
Patch 198.00	Patch: X server crashes when viewing TIFF images
OSF440X11-008	State: Existing
	This patch fixes a problem where viewing certain TIFF images with an image viewer crashed the X server.
Patch 205.00	Patch: Fix for dxaccounts BadPixmap error
OSF440CDE-009B	State: Existing
	This patch fixes a problem where the Account Manager application, dxaccounts, gets a "BadPixmap" error when selecting an account after the "View Preferences" "Display Icons By Name" option has been selected.
Patch 209.00	Patch: Static library fix for libclass.a
OSF440-131B	State: Existing
	This patch fixes a class_admin/class_daemon problem. When a PID is added to a class it cannot be removed from the class scheduler until the process terminates or the class_scheduler has been stopped.
Patch 211.00	Patch: Security (SSRT0615U)
OSF440CDE-012	State: Existing
	A potential security vulnerability has been discovered where, under certain circumstances, system integrity may be compromised. This may be in the form of improper file or privilege management. Compaq has corrected this potential vulnerability.
Patch 215.00	Patch: checklist utility does not provide scroll bar
OSF440DX-012	State: Existing
	This patch fixes a problem where the checklist utility did not provide a scroll bar on higher resolution displays (1600x1200).

Table 2–2: Summar	y of Base Operating	System Patches (cont.)

Patch 216.00 OSF440DX-013	Patch: diskconfig may display incorrectly State: Existing
	This patch fixes a problem where the Disk Configuration Manager application, diskconfig, displayed incorrectly on some non-Compaq X servers. The font used for menu items was incorrect so that the menus contained random symbols instead of text.
Patch 221.00 OSF440X11-017	Patch: Fixes problem on systems with a Powerstorm 4D10T State: Existing
	This patch fixes a problem where, on systems with a Powerstorm 4D10T (ELSA Gloria Synergy) graphics board, sometimes the X server did not draw lines correctly.
Patch 232.00	Patch: Fix for lex command
OSF440-172	State: Existing This patch fives a problem in lev that causes it to generate incorrect.
	This patch fixes a problem in lex that causes it to generate incorrect tables. This results in the lexical analyzer failing to recognize some kinds of regular expressions involving exclusive start states.
Patch 233.00	Patch: Fix for ris script
OSF440-173	State: Existing
	This patch corrects the following problems with the /usr/sbin/ris script:
	 It incorrectly queried the user for a gateway to be used to serve a specific client when no gateway was required.
	It could fail if no default route had been established.
Patch 237.00	Patch: defragment incorrect reports large free space holes
OSF440-179	State: Supersedes patch OSF440-029 (26.00) This patch corrects the following:
	 Fixes a problem with the defragment command, where the -V option is not being parsed properly.
	• Fixes the defragment program to properly report on extremely large (>4.3GB) freespace holes. Previously it would report Free space percentages larger than 100% and would add these large holes to the smallest range (<100K) instead of the largest range (>10M) where they belong.
Patch 241.00	Patch: Fix for crashes seen on ASE or TruCluster systems
OSF440-184	State: Supersedes patches OSF440-113 (89.00), OSF440-177 (235.00) This patch corrects the following:
	 Fixes system crashes seen on ASE or TruCluster systems when changing the network interfaces. The stack is not informative and the panic may be "trap: illegal instruction", or "kernel memory fault".
	 Corrects a problem where ICMP redirect packets can modify the default route.
Patch 242.00	Patch: Fix for news command
OSF440-185	State: Existing This patch fixes a problem in which the news command fails due to the appending of additional characters to file names in the /usr/news directory.
Patch 243.00	Patch: Fix for rpc.statd hang
OSF440-186	State: Existing This patch fixes a problem where rpc.statd hangs as it tries to notify dead remote systems.

Table 2-2: Sum	nmary of Base Operating System Patches (cont.)
Patch 245.00	Patch: Cannot restore system configured with backplane RAID
OSF440-188	State: Existing
	This patch fixes a problem where, when the user attempts to restore to a system configured with backplane RAID, btextract fails.
Patch 252.00	Patch: nm command causes core dump
OSF440-199	State: Supersedes patch OSF440-122A (98.00)
	This patch corrects the following:
	• Fixes the name demangling for the tools that print symbol table names generated by the C++ V6.2 compiler. This problem will only occur for most C++ objects compiled with the ANSI options.
	 Fixes a problem with nm that can cause a core dump when the LANG environment variable is set.
Patch 256.00	Patch: mkfdmn command does not report errors
OSF440-205	State: Existing
	This patch corrects a problem that resulted in the mkfdmn command not reporting errors if you attempted to create a volume with a name that is more than 31 characters long.
Patch 260.00	Patch: Fix for mailsetup command
OSF440-211	State: Existing
	This patch fixes a problem of not completing mailsetup if the hostname ends with 0 (zero). The error message produced is:
	Error creating /var/adm/sendmail/.cf: exiting
Patch 262.00	Patch: lprsetup command sets up printers incorrectly
OSF440-217	State: Existing
	This patch fixes a problem where the lprsetup command would incorrectly set up certain types of printers, such as the hp1120c,

Patch: ftp command causes core dump problem

contains an invalid macdef (macro definition).

This patch fixes a coredump problem with ftp(1) when a .netrc file

This patch fixes a problem with the fverify -n flag creating directories.

Patch: fverify command has problems creating directories

hp4000tn, or hp61.

State: Existing

State: Existing

Patch 271.00 OSF440-228

Patch 272.00

OSF440-229

Patch 281.00 OSF440-245	Patch: Fix for tmv2_notify_cbf problem State: Supersedes patches OSF440-006 (53.00), OSF440-165 (226.00), OSF440-234 (273.00)
	This patch corrects the following:
	 Fixes a panic that occurs when KZPSA resources are not available to re-enable a channel or a device after a bus reset. The panic string is:
	panic("(spo_process_rsp) ran out of memory!")
	 Fixes a problem with the KZPSA driver. A timer is not being canceled causing a panic with the following error message:
	xpt_callback: callback on freed CC
	• Fixes a problem in which the system can panic with the following message:
	KZPSA PANIC SPO_RET_CARRIER:CARRIER NOT IN USE
	 Fixes a problem with tmv2_notify_cbf messages being logged from KPBSA adapters and creating very large binary.errlog files in a clustered environment.
Patch 284.00 OSF440-248	Patch: Problem with unit attention status being missed State: Supersedes patch OSF440-100 (77.00) This patch corrects the following:
	 Fixes the problem where the tapex -L command would report failure when run on certain devices. The failure would be reported when the command was run on certain TLZ09 devices, depending on the firmware.
	 Fixes a problem that could result in unit attention status being missed.
Patch 295.00	Patch: Fix for unaligned access panic in dli_input
OSF440-260	State: Existing
	This patch fixes an unaligned access panic in dli_input.
Patch 296.00 OSF440-261	Patch: Fix for compress utility
USF 440-201	State: Existing This patch corrects a problem with the (un)compress utility that could result in either an incomplete compressed file and loss of the original uncompressed file, or an incomplete uncompressed file and loss of the original compressed file.
Patch 297.00	Patch: Fix for voldisksetup, voldiskadd, and newfs
OSF440-262A	State: Existing This patch fixes problems with the voldisksetup, voldiskadd, or newfs commands. Each will report device errors while checking for overlapping partitions where there is no overlap on that particular device.
Patch 299.00	Patch: Fix for update installation hang
OSF440-264	State: Existing This patch fixes a problem in which a hang can occur during update install.
Patch 302.00 OSF440-267	Patch: Problem with NetRAIN and HE155 (FORE) ATM cards State: Existing
	This patch fixes a NetRAIN problem when using HE155 (FORE) ATM cards. NetRAIN will fail when configuring LANE to join ELANs.

Table 2 2. Juninary of Base operating dystem rateries (cont.	Table 2-2: Summar	ry of Base Operating	System Patches	(cont.)
--	-------------------	----------------------	----------------	---------

	· · · · · · · · · · · · · · · · · · ·
Patch 306.00	Patch: Fixes Standards namespace pollution problem
OSF440-271	State: Existing
	This patch corrects some Standards namespace pollution.
Patch 308.00	Patch: Corrects an NIS client problem
OSF440-273	State: Existing
	This patch corrects a problem where an NIS client has a different shell listed for an NIS user than does the server. When the users tried to change their NIS passwords, the password change failed, but the shell was updated.
Patch 311.00	Patch: sysconfigdb incorrectly adds blank lines
OSF440-277	State: Existing
_	This patch corrects a problem in which sysconfigdb would incorrectly add or delete blank lines to or from the target file.
Patch 313.00	Patch: showfdmn may core dump
OSF440-279	State: Existing
	This patch fixes a problem in which advfs showfdmn would sometimes core dump.
Patch 314.00	Patch: Fixes callback on freed CCB panics
OSF440-281	State: Supersedes patches OSF440-025 (136.00), OSF440-247 (283.00) This patch corrects the following:
	 Fixes callback thread blocking forever in isp_enable_lun.
	 Fixes assert wait in xpt_ccb_alloc panic.
	 Fixes a problem on configurations having multiple Qlogic 1020/1040 based SCSI controllers (for example KZPBAs) and multiple CPUs. The problem could result in stalled I/O. This could be seen as a performance degradation, command timeouts, or, in the worse cases, a system hang condition.
	 Fixes callback on freed CCB panics.
Patch 315.00	Patch: Fixes performance problem on LSM mirrored volumes
OSF440-282	State: Existing
	This patch fixes a performance problem for round robin sequential reads on LSM mirrored volumes.
Patch 322.00	Patch: sendmail core dumps when sending mime-encoded files
OSF440-290	State: Existing
	This patch fixes a problem where sendmail core dumped when trying to send certain 8-bit, mime-encoded files.

Patch 323.00	Patch: Various fixes for ALPHAVME320 systems		
OSF440-291	State: Supersedes patch OSF440-108 (84.00)		
	This patch corrects the following:		
	 Fixes two problems on the ALPHAVME320 platform: 		
	 Data corruption in the VB Backplane driver. 		
	 No floppy support in the platform code. Following is the error message received during the boot when the floppy is configured at irq6: 		
	EBV16, invalid isa0 irq6		
	 Fixes three problems in the existing VB VME Backplane Driver running on AlphaVMExx platforms: 		
	 VB VME Backplane Driver does not configure when the sysconfigtab parameter, VB_MAXNODES, is less than 10. 		
	 VB VME Backplane Driver hangs and the nodes lose liveness when the sysconfigtab parameter, VB_MAXNODES, is equal to 2. 		
	 VB VME Backplane Driver Performance is unacceptable for customer applications. 		
Patch 330.00	Patch: Fix for serial line hang		
OSF440-304	State: Supersedes patch OSF440-007 (59.00)		
	This patch corrects the following:		
	 When using tip or any other method over the serial com lines to a receiver that sends frequent xoff/xon, characters are randomly repeated. 		
	• On a DECstation 2000/300, the second com port (tty01) does not get configured. An error message "ksh: /dev/tty01: cannot create" is displayed when the tty01 port is accessed.		
	 Fixes serial line hang and enables halt switch on Eiger. 		
Patch 337.00 OSF440-168B	Patch: Fix for AdvFS property list handling State: Existing		
	This patch corrects two problems in AdvFS property list handling:		
	 Creation of property lists entries in AdvFS filesets with no available mcells will result in kernel memory fault (kmf). 		
	 The get_proplist_entry function (used to disassemble the property list buffer returned by the getproplist system call) returned the incorrect name length on property list names longer than 127 characters. 		

Patch 339.00 OSF440-262B

Patch: voldisksetup incorrectly reports device errors

State: Existing

This patch fixes problems with voldisksetup, voldiskadd, or newfs commands. Each will report device errors while checking for overlapping partitions where there is no overlap on that particular device.

Patch 341.00	Patch: Fixes file permission problem for trashinfo file		
OSF440CDE-018	State: Supersedes patches OSF440CDE-005 (5.00), OSF440CDE-007 (184.00)		
	This patch corrects the following:		
	• Fixes a problem where the CDE File Manager (dtfile) sometimes left defunct processes.		
	• Fixes a problem where the Common Desktop Environment (CDE) File Manager (dtfile) did not work correctly in restricted mode.		
	 Fixes a problem in which file permissions allow any user to write to the /.dt/Trash/.trashinfo file. 		
Patch 342.00	Patch: Security (SSRT0617U)		
OSF440CDE-019A			
	A potential security vulnerability has been discovered where, under certain circumstances, system integrity may be compromised. This may be in the form of improper file or privilege management. Compaq has corrected this potential vulnerability.		
Patch 344.00	Patch: Security (SSRT0580U)		
OSF440CDE-021	State: Supersedes patch OSF440CDE-004 (4.00)		
	This patch corrects the following:		
	 A potential security vulnerability has been discovered, where, under certain circumstances, system integrity may be compromised. This may be in the form of improper file or privilege management. Compaq has corrected this potential vulnerability. 		
	• Fixes a problem where the Common Desktop Environment (CDE) Application Manager did not recreate the list of application groups at login. After customizing the application groups, users would see the old groups instead of the new groups.		
Patch 350.00	Patch: Shared library fix for svn widget		
OSF440X11-020A	State: Existing		
	This patch fixes a problem in which the svn widget of libDXm.so creates identical backgrounds and foregrounds.		
Patch 351.00	Patch: Provides missing compose definitions		
OSF440X11-021	State: Supersedes patches OSF440CDE-014 (212.00), OSF440CDE-017 (340.00), OSF440X11-019 (223.00)		
	This patch corrects the following:		
	 Adds the ISO8859-15 functionality to the main Xresource file on the system and to the specific dtlogin resource file. With these changes, X applications have ISO8859-15 locale support integrated directly into the application. 		
	 Adds Catalan (ISO8859-15) to the list of languages from which users can choose when logging in. The additional item identifies the Catalan Latin-9 locale, which supports the Euro currency sign. 		
	 Implements Xlocales definitions that allow X applications to run under the ISO8859-15 locales. Using ISO8859-15 locales allows users to enter and use newly defined ISO8859-based characters such as the Euro monetary symbol. 		
	 Provides missing compose definitions when in ISO8859-15 based locales for the scaron, Scaron, zcaron, and Zcaron characters. 		
Patch 353.00	Patch: Fix for Turkish F keyboard problem		

OSF440X11-023

State: Existing

This patch fixes the Turkish F keyboard problem, where the character Ccedilla and ccedilla cannot be entered from the keyboard directly.

Table 2-2: Summary of Base Operating System Patches (cont.)

Patch 355.00 OSF440X11-025A	Patch: Various fixes for X font server State: Existing
	This patch fixes various problems with the \boldsymbol{X} font server and with the \boldsymbol{X} server's interaction with \boldsymbol{X} font servers.
Patch 358.00	Patch: X server incorrectly includes DPSExtension
OSF440X11-028	State: Existing This patch fixes a problem where the X server would include the Adobe Display PostScript extension (Adobe-DPS-Extension, DPSExtension) in its response to a ListExtensions request even though Display PostScript is not supported in Tru64 UNIX V4.0F.
Patch 381.00	Patch: Security (SSRT0624U)
OSF440-327	State: Existing A potential security vulnerability has been discovered where, under certain circumstances, system integrity may be compromised. This may be in the form of improper file or privilege management. Compaq has corrected this potential vulnerability.
Patch 390.00	Patch: Prevents vold from core dumping
OSF440-339	State: Existing This patch prevents /sbin/vold from dumping core during an execution of a volprint or other query command.
Patch 395.00 OSF440-344	Patch: mdir command displays year 2000 date incorrectly State: Existing
	This patch fixes a problem in which the mdir command displays the date incorrectly for the year 2000.
Patch 396.00	Patch: Problem with DE500 interfaces using ML6694F PHY
OSF440-345	State: Existing This patch corrects a problem with some DE500 interfaces that use the Micro Linear ML6694F PHY.
Patch 400.00	Patch: NetRAIN devices fail to come up after reinet restart
OSF440-349	State: Existing This patch fixes a problem of NetRAIN devices failing to come up after the reinet restart command is entered.
Patch 402.00 OSF440-351	Patch: Fixes hang in shutdown process State: Existing
	This patch fixes a hang in the shutdown process ("shutdown now") of a system when a device has flow control switched off.
Patch 405.00	Patch: Fixes a tftpd problem
OSF440-354	State: Existing This patch fixes a tftpd problem when responding to a broadcast read request and it adds the -b ption to control whether to respond to any broadcasts.
Patch 406.00 OSF440-355	Patch: Fixes a kernel memory fault when using ATM State: Supersedes patch OSF440-316 (374.00) This patch corrects the following:
	• Fixes a problem in the ATM atm_cmm_connect API routine when trying to create a VC.
	• Fixes a kernel memory fault when using ATM.
Patch 409.00 OSF440-358	Patch: Fixes a problem with NCR810 script State: Existing
	This patch fixes a problem with the NCR810 script that can cause the KZPAA/NCR810 to hang.

Table 2-2: Summ	nary of Base Operating System Patches (cont.)
Patch 419.00 OSF440-368	Patch: Updates FORE ATM (lfa) driver to Rev. V1.0.17 State: Supersedes patches OSF440-078 (72.00), OSF440-198 (251.00) This patch corrects the following:
	• Updates the FORE ATM (lfa) driver to Revision V1.0.14.
	 Updates the lfa ATM driver to V1.0.16 and fixes the following two ATM driver problems:
	 Fixes a soft hang that can occur when running NFS over ATM.
	 Allows the ATM subsyst.
	 Updates the lfa ATM device driver to V1.0.17 and adds some enhancements as well as a fix for a kernel memory fault seen when either shutting down or restarting the device driver.
Patch 420.00	Patch: quotactl prototype is now POSIX compliant
OSF440-369	State: Supersedes patch OSF440-137 (111.00)
	This patch corrects the following:
	 Fixes a problem where the system can panic with a "kernel memory fault" in dqget.
	• Changes the quotactl prototype in /usr/include/ufs/quota.h to meet POSIX standards.
Patch 434.00	Patch: file cmd fails to show filenames starting with period
OSF440-384	State: Existing
	This patch fixes a problem with the find command. Find fails to show filenames that start with a period.
Patch 435.00	Patch: Adds missing prototype for stime function
OSF440-385A	State: Existing
	This patch adds the missing prototype for the stime() function to <sys time.h="">, allowing C++ programs and other software to properly resolve it.</sys>
Patch 437.00	Patch: Fix for restore command
OSF440-387	State: Existing
	This patch fixes a problem in which the restore command can fail with the following error:
	Cannot malloc space for property list
Patch 443.00	Patch: Danish locale now uses all lowercase month names
OSF440-395	State: Existing
	This patch updates the Danish (da_DK.ISO8859-1) locale to use all lowercase month names.
Patch 444.00	Patch: Fixes sort problem when running in Japanese locale
OSF440-396	State: Supersedes patch OSF440-051 (45.00), OSF440-283 (316.00) This patch corrects the following:
	• Fixes a problem in which sort -i a_file >b_file aborts with message "A line of the input file contains more than 20480 characters" when LANG = da_DK.ISO8859-1.
	 Fixes a problem in which sort command aborts with message "A line of the input file contains more than 20480 characters" when running in a Japanese locale.
	 Fixes a problem that sometimes occurs when sorting large data files in a multibyte locales such as Japanese.

Patch	447.00
OSF4	10-399

Patch: Fixes a problem with the psiop driver **State:** Supersedes patch OSF440-163 (225.00)

This patch corrects the following:

Fixes a panic when using the scu command. When formatting a floppy using the scu command the system panics with the following error message:

System Uncorrectable Machine Check 660 (retry set)

Fixes a problem with the psiop driver that causes it to fail when vdump is used. The following error is displayed:

vdump: unable to write to device

Patch 448.00 OSF440-400

Patch: btcreate does not wait long enough between vdumps State: Supersedes patches OSF440-285 (318.00), OSF440-171 (231.00), OSF440-343 (394.00)

This patch corrects the following:

- Fixes a problem with the btcreate command where it does not pass the full pathname to newfs.
- Corrects a problem in the btextract script which could result in the failure of the script due to a problem in the use of the grep utility in the script.
- Fixes a problem with the btcreate command where default restore fails if disklabel is different.
- Fixes a problem with btcreate not waiting long enough for the next tape to be loaded with some media changers.

Patch 449.00 OSF440-401

Patch: Fix for C shell problem

State: Supersedes patches OSF440-114 (90.00), OSF440-009 (168.00), OSF440-226 (269.00)

- Corrects how the C shell handles 2-byte characters when running in the Japanese SJIS locale.
- Corrects the printing of Japanese SJIS strings that are assigned to shell variables in the C shell (csh).
- Fixes a problem in the C shell (csh) in which a segmentation fault will occur when the user defines an environmental variable which exceeds the 2048 character limitation. This limit has been lengthened to 8192 characters.
- Fixes a C shell problem where multibyte characters may not be displayed properly inside quotes.

Patch 450.00 OSF440-402	Patch: Fixes several DEC C compiler problems State: Supersedes patches OSF440-134 (108.00), OSF440-293 (325.00) This patch corrects the following:	
	• A compiler problem that allowed the generation of EV67 (CIX) instructions to be generated when using the -arch ev6 switch.	
	 A compile time performance problem with a very large (1.6 MB) array initialization. 	
	 An optimization problem that caused incorrect output when using a signed char in a strcpy-like routine, if compiled using -O4 or higher. 	
	• A compile-time error for a source line such as $a = strcpy(b,c) + 7$.	
	• An optimizer problem that caused an unintended sign-extension in the Perl program. This caused an "op/pack" failure in test 9.	
	• A compiler crash when compiling Xemacs 21.1.4 with -O4.	
	 An optimizer problem in loop unrolling that suppressed intermediate updates to induction variables under certain conditions. 	
	 A particular short parameter assignment caused incorrect run-time result. 	
	• An assignment of type $k = (char)(l >> 8)$ was not sign-extended.	
	 An optimizer problem that produced incorrect code when certain bounds checking within a loop was moved outside the loop. 	
	• An optimizer problem that caused the wrong result when compiled at -O2, under certain conditions.	
	 A virtual memory exhausted error when compiling the Open Source encryption library OpenSSL. 	
	 A compiler crash under certain conditions that produces an "Assertion failure: Non-Arithmetic Data Type" error. 	
Patch 461.00	Patch: Cursor is displayed incorrectly	
OSF440-416	State: Existing This patch fixes a problem where the cursor is displayed incorrectly when the image plane is set to 1 and the mask plane is set to 0.	
Patch 465.00	Patch: Security (SSRT0617U)	
OSF440CDE-019B	8	
	A potential security vulnerability has been discovered where, under certain circumstances, system integrity may be compromised. This may be in the form of improper file or privilege management. Compaq has corrected this potential vulnerability.	
Patch 468.00	Patch: Static library fix for svn widget	
OSF440X11-020B	State: Existing This patch fixes a problem in which the svn widget of libDXm.so creates identical backgrounds and foregrounds.	
Patch 469.00	Patch: Fix for X server interaction with X font server	
OSF440X11-025B	State: Existing This patch fixes various problems with the X font server and with the X server's interaction with X font servers.	
-		

Patch 470.00	Patch: Problem with X server interaction
OSF440X11-025C	State: Supersedes patch OSF440X11-003 (63.00) This patch corrects the following:
	 Fixes a problem where the X font server (xfs) sometimes failed with a segmentation fault when it received an invalid request.
	 Fixes various problems with the X font server and with the X server's interaction with X font servers.
Patch 474.00	Patch: stime function does not compile under C++
OSF440-385B	State: Existing This patch adds the missing prototype for the stime() function to <sys time.h="">, allowing C++ programs and other software to properly resolve it.</sys>
Patch 475.00	Patch: Fixes kernel panic occuring in lockmode 4
OSF440-425	State: Existing This patch fixes a kernel panic seen when running Classical IP over the lfa ATM driver. This panic would only occur in lockmode 4. If not in lockmode 4, the symptom would be a CPU hang.
Patch 476.00	Patch: Performance issues on EV6 SMP machines
OSF440-411B	State: Supersedes patch OSF440-054B (71.00) This patch corrects the following:
	 Fixes problems in the DECthreads library for Tru64 UNIX. Included in this patch are changes to support Ladebug enhancements and a bug fix for applications which employ SCS threads of different priorities.
	 Addresses performance and scalibility issues for highly contended threaded applications running on EV6 SMP machines.
Patch 478.00	Patch: Fix for LAT driver
OSF440-437	State: Existing This patch corrects a problem in the LAT driver which caused improper processing of the ioctl TCSBRK as well as the generation of spurious <break> characters when the libc routine tcdrain() was used.</break>
Patch 480.00 OSF440-488	Patch: Extends max length of identifier for assembler State: Supersedes patch OSF440-365 (416.00) This patch corrects the following:
	 Resolves a problem that caused the assembler to flag any identifiers whose length exceeded 1024 characters with an assembly-time error. With this patch, such identifiers are now accepted.
	 Corrects a problem where the assembler would generate incorrect error messages for source programs that produce a mix of hand-coded and assembler-generated relocation operands.
Patch 482.00 OSF440-459	Patch: Fix for mailx problem State: Existing This patch corrects the problem so mailx(1) will work correctly if the -r and -s flags are used together.
Patch 507.00	Patch: NFS writes cause protocol violations
OSF440-436B	State: Existing This patch fixes reply values for NFS writes which were causing protocol violations.

Table 2–2: Summary of Base Operating System Patches (cont.)	
Patch 513.00	Patch: Fix for the dtfile ICDE COSE tool
OSF440CDE-022A	State: Supersedes patch OSF440CDE-020A (343.00)
	This patch corrects the following:
	• Fixes a problem in which dtfile ICDE COSE tool of

does not work when TMPDIR is defined as /ldata/disk_local/tmp. dtfile returns this error:

/ldata/disk_local/tmp/sdtdbcache_AAAaadmma: Cross-device link /ldata/disk_local/tmp/sdtdbcache_BAAaadmma: Cross-device link Floating exception (core dumped)

Fixes a problem with the Common Desktop Environment (CDE) in which some desktop applications will fail if CDE is not initialized. The error which appears in the users home .dt/errorlog file is:

Desktop Not Initialized: Could not createAction/Datatypes database.

Patch 515.00	Patch: Fix for umount command
OSF440-443	State: Existing
	This patch prevents a "not currently mounted" warning message from being displayed for filesystems the user did not request to umount.
Patch 526.00	Patch: Fix for kernel memory fault
OCE 440 401	

OSF440-461 **State:** Existing

This patch fixes a kernel memory fault that affects linear machines such as ebm30, GS160 through GS320, DS10, DS20, ES40, and XP1000.

Patch 528.00 **Patch:** Security (SSRT0571U) OSF440CDE-023

routes.

State: Supersedes patches OSF440CDE-001 (1.00), OSF440CDE-002 (2.00)

- · A potential security vulnerability has been discovered where, under certain circumstances, users may gain unauthorized access. Compaq has corrected this potential vulnerability.
- Fixes a problem where the CDE mail interface (dtmail) does not display the date and time of mail messages in the Message Header list when the time zone is set to certain time zones such as GB-Eire.
- Fixes a dtmail problem in which a From line with quotes in it incorrectly finds the date of the mail message. This error is displayed on the main screen under the header Date and Time and

	shows up as Dec. 31 or as a blank field.
Patch 530.00	Patch: Fix for Y2K lastlogin command problem
OSF440-441	State: Existing
	This patch resolves the Y2K problem of lastlogin command incorrectly calculating the last date each user logged in.
Patch 532.00	Patch: Fix for slow shutdowns due to name lookups
OSF440-426	State: Existing
	This patch corrects slow shutdown due to name lookups while deleting

Table 2-2: Summary of Base Operating System Patches (cont.)

Patch 537.00 OSF440CDE-024

Patch: Security (SSRT0600U)

State: Supersedes patches OSF440CDE-006 (6.00), OSF440CDE-008 (185.00), OSF440CDE-025 (535.00)

This patch corrects the following:

- A potential security vulnerability has been discovered where, under certain circumstances, system integrity may be compromised. This may be in the form of improper file or privilege management. Compaq has corrected this potential vulnerability.
- Fixes a problem where dtlogin may incorrectly set the permissions of /var to 775. It also fixes a problem where dtlogin may incorrectly set the umask to 002 for csh users.
- Fixes a problem with the Common Desktop Environment (CDE) login process where if you selected the Command Line Login option and logged in, sometimes the CDE login screen would be redisplayed before you had logged out.
- Fixes a problem where the Common Desktop Environment (CDE) login daemon, dtlogin, core dumps occasionally when servicing requests from XDMCP clients such as X terminals or PCs running X servers.

Patch 542.00 OSF440X11-034A

Patch: X Server may generate an Invalid Pixmap Error **State:** Supersedes patches OSF440X11-002A (62.00), OSF440X11-011A (218.00)

This patch corrects the following:

- Fixes a problem with Motif Drag-and-Drop where, if a parent drop site was unregistered before a child drop site, subsequently unregistering the child drop site would cause a segmentation fault.
- Fixes a problem with the toggle button where, if a display is closed and reopened, then the X Server may generate an "Invalid Pixmap Error".
- Fixes various memory leaks in the Motif library (libXm) that could occur when creating and destroying Motif List, Text, and TextField widgets.

Patch 544.00 OSF440-455

Patch: Security (SSRT0567U, SSRT0590U)

State: Supersedes patches OSF440-014 (12.00), OSF440-109 (85.00), OSF440-412 (458.00)

- A potential security vulnerability has been discovered where, under certain circumstances, system integrity may be compromised. This may be in the form of improper file or privilege management. Compaq has corrected this potential vulnerability.
- Fixes a problem where some crontab jobs would run multiple times in the same minute.
- Fixes two cron problems:
 - The cron daemon does intensive logging and fills up the disk.
 - Multiple cron daemons continue to run and consume system resources due to the fact that after a user is deleted from the system there are still jobs running on the user's behalf.

Patch	546.00
OSF4	40-422

Patch: Incorrect results when using disk statistics tools

State: Supersedes patches OSF440-005 (44.00), OSF440-224 (267.00), OSF440-238 (277.00), OSF440-255 (290.00), OSF440-319 (333.00), OSF440-298 (363.00), OSF440-308 (367.00), OSF440-406 (454.00)

This patch corrects the following:

- Fixes a kmf problem in bucket 2 (64 byte bucket) when the type of SCSI device dynamically changes.
- Corrects a problem in which the wrong status could be returned when using a tape device.
- Increases the performance of random I/O on the HSG80 disk controller.
- Fixes a problem in which the system can panic with a kernel memory fault.
- Fixes the following problems:
 - Continuous resets when an I/O command is causing the resets
 - Read capacity recovery failure
 - Bad block replacement (BBR) processing
 - Fixes a problem where programs that read, analyze and monitor disk statistics (such as collect) will occasionally display incorrect results.
 - Fixes a problem in which the system can panic with a kernel memory fault during an installation with an HSZ70 or HSZ80 connected to the system.
 - Fixes a problem when the type of SCSI device dynamically changes, which can result in a kernel memory fault or memory corruption panic.
- Fixes a simple lock panic.

Patch 548.00 OSF440-438

Patch: Fix for advscan

State: Existing

This patch fixes a problem where advscan -a -g does not display bootable partitions properly.

Patch 551.00 OSF440-466

Patch: Fixes problems with the mv command

State: Supersedes patches OSF440-371 (422.00), OSF440-474 (549.00) This patch fixes the following problems with the my command:

- An invalid error message when attempting to move files in which the source name is the same as the destination name.
- When using my -i to rename a symlink pointing to a file on a different filesystem owned by a different user, it results in the prompt:

Ownership of y will change. Continue?

- When moving a file from one filesystem to another, the mv command will copy the file rather than using the rename() system call. This can result in file loss.
- Corrects the problem with the mv(1) command deleting files in the directory when the user moves a directory to itself.

Table 2–2: Summary of Base Operating System Patches (cont.)

Patch 553.00	Patch: Static library fix (libXt)	
OSF440X11-033A	State: Supersedes patches OSF440X11-005B (206.00), OSF440X11-018B (336.00) This patch corrects the following:	
	 Fixes a memory leak in the X Toolkit library (libXt). This memory leak could be seen by applications that create and destroy many Motif ScrolledWindow widgets 	
	 Fixes a memory leak in the X Window System's X Toolkit library (Xt) that could occur when creating and destroying Motif List, Text, and TextField widgets. 	
Patch 555.00	Patch: Fix for salvage utility	
OSF440-433	State: Existing	
	This patch corrects several known problems with salvage:	
	Fixes two infinite loops that could make salvage run forever.	
	• salvage could core dump when encountering a deleted property list.	
	Removes garbage characters from symlink recovery in salvage.	
Patch 557.00	Patch: Fix for what command	
OSF440-472	State: Existing	
	This patch fixes a problem with the what command. This command was unable to process more than one input file at once.	

Patch 559.00 OSF440DX-019

Patch: Fix for dxaccounts application

State: Supersedes patches OSF440DX-004 (189.00), OSF440DX-005 (190.00), OSF440DX-006 (191.00), OSF440DX-008 (193.00), OSF440DX-010 (214.00), OSF440DX-014 (345.00), OSF440DX-015 (346.00), OSF440DX-016 (347.00), OSF440DX-017 (348.00), OSF440DX-018 (349.00)

This patch corrects the following:

- Fixes two situations in which the GUI account management program (dxaccounts) will crash in a Enhanced Security client environment when attempting to copy an NIS user account.
- Fixes the problem with the useradd, usermod, userdel commands removing the last entry of the /etc/passwd file when the last line of the /etc/passwd file does not end with the new line character (\n).
- Fixes a problem where usermod -D can coredump if an NIS group entry contains a large number of users.
- Fixes a problem in which the command usermod was not allowing any commas in the comment field when the current GECOS fields are filled.
- Fixes a problem in which a duplicate user identifier (UID) is accepted at a second attempt even if the no-duplicat-user-identifier policy is set.
- Updates the error message displayed when Account Manager fails to start due to the detection of an Account Manager lock file (/etc/.AM_is_running) on the system.
- Fixes the problem in which a command usermod -D does not display the Expire date when it is set.
- Fixes a problem in which dxaccounts does not allow the system manager to add NIS users when the system is running enhanced security.
- Fixes the problem of enabling to change root's login/uid through cli/dxaccounts utilities.
- Fixes a problem in which the dxaccounts application does not allow users to be added to groups with Group ID lower than the default minimum specified in the General Options dialog.
- Fixes a problem where the new home directory for a new user ID is created with the date and time stamp of the /usr/skel directory.

Patch 561.00 OSF440-428

Patch: Fix for system panic

State: Existing

This patch fixes a problem where encoding for the SysV Open call audit parameter was incorrect. This could cause a system panic.

Patch 564.00 OSF440-439A Patch: Security (SSRT0642U)

State: Supersedes patches OSF440-149A (123.00), OSF440-251A (287.00), OSF440-301A (364.00), OSF440-370A (421.00), OSF440-462A (562.00)

This patch corrects the following:

- Fixes a problem of libsecurity producing a core file when handling error conditions.
- A potential security vulnerability has been discovered where, under certain circumstances, system integrity may be compromised. This may be in the form of improper file or privilege management. Compaq has corrected this potential vulnerability.
- Corrects a problem of the rsh command displaying a warning message instead of the rsh command output when C2 security is configured.
- Fixes a problem with logins in a DCE/C2 environment. You could encounter an error "Bad priority setting" if there is a u_priority setting used in /etc/auth/system/default file.
- Fixes a problem for Enhanced Security configurations where the Maximum Login Interval (u_max_login_intvl) field was being ignored for account templates.
- Fixes a problem when a system is configured with DECnet, C2, and NIS. When invoking edauth(8), the error "Must be on NIS master server to update entry for <user_name>" is returned.

Patch 567.00 OSF440-439B Patch: Security (SSRT0642U)

State: Supersedes patches OSF440-149B (203.00), OSF440-251B (338.00), OSF440-301B (472.00), OSF440-370B (473.00), OSF440-462B (565.00)

- Fixes a problem of libsecurity producing a core file when handling error conditions.
- A potential security vulnerability has been discovered where, under certain circumstances, system integrity may be compromised. This may be in the form of improper file or privilege management. Compaq has corrected this potential vulnerability.
- Corrects a problem of the rsh command displaying a warning message instead of the rsh command output when C2 security is configured.
- Fixes a problem with logins in a DCE/C2 environment. You could encounter an error "Bad priority setting" if there is a u_priority setting used in /etc/auth/system/default file.
- Fixes a problem for Enhanced Security configurations where the Maximum Login Interval (u_max_login_intvl) field was being ignored for account templates.
- Fixes a problem when a system is configured with DECnet, C2, and NIS. When invoking edauth(8), the error "Must be on NIS master server to update entry for <user_name>" is returned.

Patch 569.00 OSF440X11-034B

Patch: Fixes a problem with the toggle button

State: Supersedes patches OSF440X11-002B (70.00), OSF440X11-011B (335.00)

This patch corrects the following:

- Fixes a problem with Motif Drag-and-Drop where, if a parent drop site was unregistered before a child drop site, subsequently unregistering the child drop site would cause a segmentation fault.
- Fixes a problem with the toggle button where, if a display is closed and reopened, then the X Server may generate an "Invalid Pixmap Error".
- Fixes various memory leaks in the Motif library (libXm) that could occur when creating and destroying Motif List, Text, and TextField widgets.

Patch 571.00 OSF440DX-020

Patch: diskconfig fails when creating an AdvFS partition

State: Supersedes patches OSF440DX-007 (192.00), OSF440DX-002 (187.00)

This patch corrects the following:

- Fixes a problem with the diskconfig utility where ri type disks were not correctly recognized.
- Fixes a problem where, when creating an AdvFS partition, the disk $\,$ configuration utility (/usr/sbin/diskconfig) failed with the error:

Error in Tcl Script

Error: can't read dskdir: no such variable

Fixes a problem that was causing diskconfig to issue the error message "can't read tminor: no such variable" upon startup.

Patch 573.00 OSF440-468

Patch: Processes hang waiting for I/O interrupts **State:** Supersedes patch OSF440-315 (373.00)

This patch corrects the following:

- Processes may hang due to waiting for I/O interrupts.
- The SCU command set pages pcf will hang a system when ATAPI CDrom device is selected.
- Corrects recognition problems with some models of IDE CD-ROM devices and removable disk devices during system startup. Some IDE devices may cause the system to hang or panic during startup and others may not be recognized.

Patch 575.00 OSF440X11-033B

Patch: Fixes memory leak in X Toolkit library

State: Supersedes patches OSF440X11-005A (195.00), OSF440X11-018A (222.00)

- Fixes various Minor System Faults (MSFs) in the X Toolkit library
- Fixes a memory leak in the X Toolkit library (libXt). This memory leak could be seen by applications that create and destroy many Motif ScrolledWindow widgets
- Fixes a memory leak in the X Window System's X Toolkit library (Xt) that could occur when creating and destroying Motif List, Text, and TextField widgets.

Patch 579.00 OSF440X11-032A

Patch: Core dump when using input method server **State:** Supersedes patches OSF440X11-010A (217.00), OSF440X11-013 (219.00), OSF440X11-024 (354.00), OSF440X11-026A (356.00)

This patch corrects the following:

- Fixes a problem in which ^C fails to work in dtterm when logged in to a 4.0E or 4.0F system using XDMCP.
- Fixes a character input problem for non-Latin-1 keyboards.
- Fixes a problem in which some 8-bit characters cannot be entered directly from the keyboard when the Caps Lock setting is on.
- Prevents a potential core dump from the X11 library when running an input method server for Japanese, Chinese, or Korean.
- Fixes two memory leaks in the X Window System's X library (Xlib) that can occur when creating and destroying Motif List, Text, and TextField widgets.

Patch 584.00 OSF440-429

Patch: System may panic when running ATM ELANs **State:** Supersedes patch OSF440-068 (147.00), OSF440-356 (407.00) This patch corrects the following:

- Fixes a problem with the creation of multiple ATM ELANS.
- Fixes a problem in which the system may panic with the error message "Unaligned kernel space access from kernel mode" when running ATM ELANs.
- When running ATM LAN Emulation, using more than four ATM NetRAIN interfaces can result in recursive calls causing a "kernel stack not valid" halt.

Patch 586.00 OSF440CDF-02

Patch: Fix for dtfile tool

OSF440CDE-022B State: Supersedes patch OSF440CDE-020B (467.00)

This patch corrects the following:

 Fixes a problem in which dtfile ICDE COSE tool does not work when TMPDIR is defined as /ldata/disk_local/tmp. dtfile returns this error:

/ldata/disk_local/tmp/sdtdbcache_AAAaadmma: Cross-device link /ldata/disk_local/tmp/sdtdbcache_BAAaadmma: Cross-device link Floating exception (core dumped)

• Fixes a problem with the Common Desktop Environment (CDE) in which some desktop applications will fail if CDE is not initialized. The error which appears in the users home .dt/errorlog file is:

Desktop Not Initialized: Could not createAction/Datatypes database.

Patch 592.00 OSF440-507

Patch: Fixes a problem with floppy driver

State: Supersedes patch OSF440-366 (417.00)

Compaq has determined in laboratory testing that there is a theoretical possibility that during read and write operations to the floppy disk on DS10, DS10L and ES40 AlphaServers and VS10 and XP900 AlphaStations, a single byte of data may be inaccurately read or written without notice to the user or system. The potential for this anomaly exists only if floppy data read and write operations are attempted while there is extremely heavy traffic on these Alpha systems' internal input/output busses. Although Compaq has observed the anomaly only in laboratory tests designed to create atypical system stresses, including almost constant use of the floppy disk drive, we are supplying this patch to address this potential issue.

Table 2–2: Summary of Base Operating System Patches (cont.)

Patch 594.00 OSF440X11-032B

Patch: Core dump when using multibyte-character locale **State:** Supersedes patches OSF440X11-010B (334.00), OSF440X11-026B (471.00)

This patch corrects the following:

- Fixes a problem in which ^C fails to work in dtterm when logged in to a 4.0E or 4.0F system using XDMCP.
- Fixes a character input problem for non-Latin-1 keyboards.
- Fixes a problem in which some 8-bit characters cannot be entered directly from the keyboard when the Caps Lock setting is on.
- Prevents a potential core dump from the X11 library when running an input method server for Japanese, Chinese, or Korean.
- Fixes two memory leaks in the X Window System's X library (Xlib) that can occur when creating and destroying Motif List, Text, and TextField widgets.

Patch 596.00 OSF440CDE-026

Patch: Fix for dtwm hang

State: Existing

This patch fixes a problem in which the Window Manager (dtwm) intermittently hangs on a system which uses multiple displays.

Patch 598.00 OSF440-430

Patch: Fix for tapex utility

State: Existing

This patch fixes several problems in the tapex utility;

- Accuracy of performance tests has been improved.
- The tapex exit status has been corrected.
- tapex was fixed to determine eom status in Command Timeout Test and exit with non-0 status to indicate failure.

Patch 640.00 OSF440-549

Patch: Security (SSRT0563U, SSRT0676U)

State: Supersedes patches OSF440-037 (139.00), OSF440-121 (97.00), OSF440-038 (140.00), OSF440-044 (39.00), OSF440-087 (165.00), OSF440-167 (228.00), OSF440-266 (301.00), OSF440-445 (590.00), OSF440-004 (34.00), OSF440-011 (9.00), OSF440-012 (10.00), OSF440-015 (13.00), OSF440-003 (27.00), OSF440-032 (30.00), OSF440-061 (55.00), OSF440-120 (96.00), OSF440-123 (99.00), OSF440-128 (102.00), OSF440-132 (106.00), OSF440-133 (107.00), OSF440-136 (110.00), OSF440-142 (116.00), OSF440-143 (117.00), OSF440-148 (122.00), OSF440-152 (126.00), OSF440-155 (129.00), OSF440-039 (141.00), OSF440-067 (146.00), OSF440-081 (160.00), OSF440-085 (164.00), OSF440-095 (174.00), OSF440-033A (31.00), OSF440-099 (178.00), OSF440-104A (81.00), OSF440-138 (112.00), OSF440-164 (134.00), OSF440-158 (224.00), OSF440-170 (230.00), OSF440-180 (238.00), OSF440-182 (239.00), OSF440-187 (244.00), OSF440-194 (248.00), OSF440-204 (255.00), OSF440-206 (257.00), OSF440-209 (259.00), OSF440-221 (265.00), OSF440-227 (270.00), OSF440-256 (291.00), OSF440-259 (294.00), OSF440-268 (303.00), OSF440-272 (307.00), OSF440-276 (310.00), OSF440-278 (312.00), OSF440-284 (317.00), OSF440-144 (118.00), OSF440-036 (33.00), OSF440-056 (49.00), OSF440-057 (50.00), OSF440-058 (51.00),

Table 2–2: Summary of Base Operating System Patches (cont.)

Patch 640.00 continued

OSF440-059 (52.00), OSF440-112 (88.00), OSF440-125 (100.00), OSF440-141 (115.00), OSF440-147 (121.00), OSF440-060A (54.00). OSF440-082 (161.00), OSF440-305 (331.00), OSF440-166 (227.00), OSF440-174 (234.00), OSF440-208 (258.00), OSF440-213 (261.00), OSF440-220 (264.00), OSF440-244 (280.00), OSF440-257 (292.00), OSF440-265 (300.00), OSF440-289 (321.00), OSF440-097A (176.00), OSF440-303 (329.00), OSF440-168A (229.00), OSF440-107 (83.00), OSF440-191 (246.00), OSF440-159 (131.00), OSF440-088 (73.00), OSF440-065 (58.00), OSF440-207 (180.00), OSF440-239 (210.00), OSF440-253 (288.00), OSF440-269 (304.00), OSF440-288 (320.00), OSF440-294 (326.00), OSF440-018 (16.00), OSF440-157 (130.00), OSF440-314 (332.00), OSF440-073 (152.00), OSF440-219 (263.00), OSF440-116 (92.00), OSF440-070 (149.00), OSF440-071 (150.00), OSF440-216 (181.00), OSF440-196 (250.00), OSF440-240 (278.00), OSF440-270 (305.00), OSF440-110 (86.00), OSF440-292 (324.00), OSF440-160 (132.00), OSF440-200 (360.00), OSF440-297 (362.00). OSF440-302 (365.00), OSF440-307 (366.00), OSF440-309 (368.00), OSF440-310 (369.00), OSF440-311 (370.00), OSF440-312 (371.00), OSF440-313 (372.00), OSF440-317 (375.00), OSF440-320 (377.00), OSF440-322 (379.00), OSF440-324 (380.00), OSF440-328 (382.00), OSF440-335 (388.00), OSF440-337 (389.00), OSF440-340 (391.00), OSF440-341 (392.00), OSF440-342 (393.00), OSF440-346 (397.00), OSF440-347 (398.00), OSF440-348 (399.00), OSF440-352 (403.00), OSF440-353 (404.00), OSF440-360 (411.00), OSF440-361 (412.00), OSF440-362 (413.00), OSF440-363 (414.00), OSF440-367 (418.00), OSF440-372 (423.00), OSF440-373 (424.00), OSF440-374 (425.00), OSF440-375 (426.00), OSF440-379 (429.00), OSF440-380 (430.00), OSF440-382 (432.00), OSF440-383 (433.00), OSF440-393 (441.00), OSF440-394 (442.00), OSF440-397 (445.00), OSF440-398 (446.00), OSF440-405 (453.00), OSF440-407 (455.00), OSF440-414 (459.00), OSF440-415 (460.00), OSF440-417 (462.00), OSF440-295 (327.00), OSF440-250 (286.00), OSF440-331 (385.00), OSF440-419 (464.00), OSF440-418 (463.00), OSF440-364 (415.00), OSF440-408 (456.00), OSF440-135 (109.00), OSF440-140 (114.00), OSF440-225 (268.00), OSF440-263 (298.00), OSF440-434 (483.00), OSF440-424 (484.00), OSF440-436A (485.00), OSF440-457 (486.00), OSF440-480 (487.00), OSF440-458 (488.00), OSF440-447 (489.00), OSF440-483 (490.00), OSF440-450 (491.00), OSF440-481 (492.00), OSF440-435 (493.00), OSF440-454 (494.00), OSF440-427 (495.00), OSF440-456 (496.00), OSF440-477 (497.00), OSF440-449 (498.00), OSF440-471 (499.00), OSF440-442 (500.00), OSF440-482 (501.00), OSF440-446 (502.00), OSF440-465 (503.00), OSF440-469 (505.00), OSF440-063 (57.00), OSF440-075 (154.00), OSF440-476 (519.00), OSF440-534 (599.00), OSF440-578 (600.00), OSF440-579 (601.00), OSF440-514 (602.00), OSF440-559 (603.00), OSF440-554 (604.00), OSF440-550 (605.00), OSF440-492 (606.00), OSF440-489 (607.00), OSF440-567 (608.00), OSF440-605 (609.00), OSF440-544A (610.00), OSF440-574 (611.00), OSF440-530 (612.00), OSF440-500 (613.00), OSF440-490 (614.00), OSF440-577 (615.00), OSF440-540 (616.00), OSF440-585A (617.00), OSF440-569 (618.00), OSF440-546 (619.00), OSF440-497 (620.00), OSF440-503 (621.00), OSF440-505 (622.00), OSF440-522 (623.00), OSF440-487 (624.00), OSF440-562 (625.00), OSF440-460 (626.00), OSF440-560 (627.00), OSF440-570 (628.00), OSF440-558 (629.00), OSF440-553 (630.00), OSF440-543 (631.00), OSF440-536 (632.00), OSF440-491 (633.00), OSF440-557 (634.00), OSF440-617 (635.00), OSF440-525 (636.00), OSF440-501 (637.00), OSF440-504 (638.00)

Patch 640.00 continued

This patch corrects the following:

- Fixes a kernel problem where proper locking/reference count management was not being performed. This could result in a "lock-terminate: lock held" system panic.
- Fixes invalid malloc message in mfs.
- Fixes a problem with the newfs command. When the newfs -N command was run on a mounted file system, it returned an error message similar to the following:

newfs: /dev/rrz0c: is marked in the disklabel as in use by: 4.2BSD

- Fixes a problem where a system panic will occur when accessing an ISO9660 format CD-ROM.
- Fixes a problem with CDFS. Data corruption occurs when reading beyond the end of a partition.
- Fixes a problem in which the system may memory fault if the TCR/ASE server no longer had access to the CD-ROM device.
- Fixes a problem where the system can panic with the panic string "secsize_resid < d_reclen" when accessing a defective CD-ROM.
- Fixes a problem with CDFS. Fatal errors occur when trying to load data from a CDFS CD-ROM over NFS.
- Fixes a panic seen when accessing the kio subsystem (such as with consvar) with improper arguments. The panic was caused by a kernel double-free, and would most likely be seen as a corruption in either the 64- or 96-byte bucket (buckets 2 and 16).
- Fixes a problem where process accounting data was not written to the accounting file when it was on an NFS-mounted file system.
- Corrects a "simple_lock: time limit exceeded" panic in softclock_scan().
- Fixes a kernel memory fault from socket code. The kernel memory fault results from failing to get a lock on a list of threads that have requested resources on a socket.
- Corrects a problem where a signal is delivered, but not responded to, by the target process.
- Fixes a panic of "get_color_bucket: empty buckets" when the sysconfig attribute "private-cache-percent" is non-zero.
- A potential security vulnerability has been discovered where, under certain circumstances, users may gain unauthorized access. Compaq has corrected this potential vulnerability.
- Fixes a problem with the mount command where it sometimes kills other processes.
- Fixes a problem where process accounting data was not written to the accounting file when the accounting file was on an NFS-mounted file system.
- Fixes problems with loadable drivers indicated by a maximum device number, lack of device number 0, or failure to reconfigure or reload a driver.
- Removes a Granularity Hint Regions (also called GH chunks) restriction which may be encountered on AlphaServer DS20 and ES40 systems running the Tru64 UNIX V4.0F release. This restriction can reduce performance for certain database applications.

Patch 640.00 continued

- Fixes several problems associated with Controller Reset (hard-error recovery) for the KZPCC backplane RAID controller.
- Fixes a problem in which mount would incorrectly fall back to Version 2 after certain errors had been encountered using Version 3.
- Fixes an nfs/ufs/vm deadlock. While serving a client, the system running ASE/DT as an NFS server can hang with deadlock.
- Fixes a problem in which the system may panic with the error message "kernel memory fault".
- Fixes several KZPCC RAID controller problems which in turn provides full support of the product.
- Fixes a problem where applications using the fcntl() system calls may appear to hang.
- Fixes "simple_lock: time limit exceeded" panics.
- Fixes two problems: fork can fail to obtain swap space and the resource limitation on core files does not work as documented.
- Fixes a problem where the system can panic with the following console message:

bs_bf_htop: invalid handle \n N1 = 0

- Fixes a system pause seen when doing a lot of I/O to UFS filesystems.
- Fixes a problem that causes system panics when thread_swappable
 is called with the current_thread as the target thread, when the
 thread is about to be swapped out.
- This work provides functionality to allow detecting unlinked referenced files.
- Fixes a problem with the map entry indexing scheme that results in the following panic:

pmap_release_page: page not found

- Fixes a problem in which certain invalid kernel address ranges may get ignored. This can result in invalid kernel memory accesses to be left unnoticed.
- Fixes a problem that causes the Tru64 UNIX Version 5.0 update install procedure to exit with core dumps and /sbin/loader failures on a system.
- Fixes a problem in the module core() that can cause a panic with the message:

vrele: bad ref count

- Fixes two separate problems:
 - A panic in the kernel with the following error message:

simple_lock: time limit exceeded

 A panic occurs when booting kernel interactively and setting the memlimit. The panic error message is as follows:

kernel memory fault

 Fixes a problem with kdbx. A core file created by kdbx was left in the root directory when recovering from a system crash.

Patch 640.00 continued

- Removes a Granularity Hint Regions (also called GH chunks) restriction which may be encountered on AlphaServer DS20 and ES40 systems running the Tru64 UNIX V4.0F release. This restriction can reduce performance for certain database applications.
- Fixes several problems associated with Controller Reset (hard-error recovery) for the KZPCC backplane RAID controller.
- Fixes a system hang condition. All NFS-related services may deadlock.
- Fixes the database application core dumps when using truss/trace tools by remembering that COW has been set up on a shared pte and processes it correctly when a subsequent write access is made to the page.
- Fixes a data corruption problem that can occur when mapping to private regions.
- Fixes a problem where AS1200 systems with more than three pairs of memory displays the following warning message on the console during boot:
 - pmap_get_align: Unaligned memory hole found... Please reset the system to clear any previous memlimit
- Fixes a kernel memory fault caused when a network application walked an inpq array.
- Fixes a problem in which signals can be lost in multithreaded applications.
- Fixes a problem that only occurs if real-time preemption is enabled and SMP test suites are run.
- Fixes a problem that could result in a incorrect scheduling of threads when they were dispatched from the idle state.
- Fixes a problem with virtual memory. When running the Oracle database, Oracle can not detach from a shared memory segment.
- Fixes single-step support in a debugger, such as Ladebug, for instructions that trap or fault.
- Fixes an incorrect calculation for memory-usage-by-type when kmem_debug is set.
- Fixes a simple_lock: hierarchy violation in sigq_abort() when lockmode is set to 4.
- Fixes a system panic on multi-process systems (approximately 12 CPUs) with large memory (128GB). The system can panic with:
 - panic: lock time on vm_page_free_lock
- Fixes a problem in which unmounting an NFS mounted directory can cause a user process to coredump.
- Fixes a problem where partitioned Turbolasers return incorrect CPU data for CPUs that are not in the partition.
- Corrects a problem that was causing degraded performance of the WAN Support for Tru64 UNIX layered product.
- Under certain conditions, when using Asynchronous I/O, NULL pointer can be dereferenced in aio_unwire(), causing a kernel memory fault panic. This fix eliminates this possibility.
- Fixes a problem where ubc_msync() may not flush out all the pages in the requested range.
- Fixes var adm messages from truncation on larger configurations by raising the default size (4096) of msgbuf_size to 8192.

Patch 640.00 continued

- Fixes a problem where systems with the DUV40FAS0002-19991116 patch kit installed would run low on kernel memory after process accounting had been running for a while.
- Corrects a problem where a mount(8) command failure caused the operating system to crash. Instead, the failure will now only cause the AdvFS filesystem domain to shut down.
- Fixes a problem on systems using the AdvFS filesystem, where the system can panic with the following panic string:
 - del_clean_mcell_list: no primary xtnt record
- Fixes an AdvFS domain panic that occurs with the following message on the console:
 - load_x_cache: bad status from bs_refpg of sbm
- Fixes a problem with AdvFS that will cause the system to panic with "kernel memory fault" in audit_rec_build().
- Fixes a problem where the statfs system call was reporting incorrect block usage on AdvFS filesets. As a side effect of this problem, the sendmail utility may sleep needlessly (waiting for space to become available).
- Provides the following fixes and enhancements to AdvFS:
 - AdvFS volumes were not setting the default I/O byte transfer size to the preferred size reported by the disk drives.
 - AdvFS chvol read and write transfer size range was increased.
 - The read-ahead algorithm was modified to improve performance under certain conditions.
- Fixes the problem where the system panics if AdvFS detects an inconsistency in the free list of mcells that is kept on a per-volume basis in an AdvFS domain. The panic string seen with this panic is as follows:
 - alloc mcell: bad mcell free list
- Fixes a problem where update takes too long to sync mmap files when using an AdvFS file system.
- Fixes the following two problems in AdvFS:
 - When a "log half full" or "log full" problem occurs, an entire system will panic.
 - The error message "ftx_bfdmn_recovery:bad record size\n N1 = 1" is received when the wordCnt, as returned by lgr_read, is not enough to hold the ftxDoneLRT record that precedes each log record in a log page.
- Corrects a problem where a "can't clear a bit twice" panic occurs after an unanticipated system crash and an improperly handled AdvFS recovery operation.
- Corrects a problem in AdvFS that causes single-CPU systems to hang and causes multiple-CPU systems to panic with a "simple lock time limit exceeded" error specifying lock class name BfAccessTblMutex.
- Corrects a problem in AdvFS where unmounting a domain that is already in a panicked state could result in the following system panic message:

 $log_flush_sync: pinpg error \ N1 = 5$

Patch 640.00 continued

- Fixes a problem in AdvFS. AdvFS may skip filesystem recovery after aborted domain activation.
- Corrects a kernel memory fault that occurs when entering the mount -o dual command.

Abbreviated stack:

9 XentMM()

10 bs bfdmn sweep()

11 bs_bfdmn_activate()

12 bs bfdmn tbl activate()

13 bs_bfset_activate_int()

14 bs_bfset_activate()

15 advfs_mountfs()

- Fixes a problem that may cause panics to occur when msfs_getpage() receives an error return from fs_write_add_stg() when attempting to write to an AdvFS domain that is out of disk
- Fixes a problem in AdvFS. A fileset is busy when attempting to unmount giving an EBUSY error even though the fileset has no open files.
- ASE/Disaster Tolerance systems hang when a kernel vnode reclaim flushes a vnode's modified data to disk and ASE/DT is currently suspending I/O requests.
- Fixes a problem with making a msfs_putpage() call. The length argument may get its upper bits truncated, which will result in an incorrect length calculation.
- Fixes a problem in the AdvFS system. A panic occurs with the following error message:

lock_read: hierarchy violation

- Fixes a situation in which a slight memory leak can occur when recovering Advfs domains with mount.
- Fixes a problem where a single CPU system using AdvFS can hang in cleanup_closed_list().
- Corrects AdvFS problems involving clone filesets. The statfs syscall (used by df) was incorrectly returning zero blocks USED for clones. The read-ahead code was incorrectly passing up opportunities to do read-ahead on clone filesets, resulting in a large performance penalty.
- Corrects two problems in AdvFS property list handling:
 - Creation of property lists entries in AdvFS filesets with no available mcells will result in kernel memory fault (kmf).
 - The get_proplist_entry function (used to disassemble the property list buffer returned by the "getproplist" system call) returned incorrect name length on property list names longer than 127 characters.
- Fixes a problem with soclose() that caused permanent looping on exit while aborting pending connections at a TCP/IP listener socket.
- When configuring the AlphaServer ES40, the ISA devices IDE and USB are not configured if a combo card is installed.
- The system panics with a kernel memory fault when installing on a AlphaServer DS20.

Patch 640.00 continued

- · Fixes the following Compaq AlphaServer problems:
 - On the ES40 and DS20, nonfatal 680 environment machine checks are being logged as fatal/noncorrectable errors.
 - On the DS20, a fix has been made to the handling of power supply, temperature, and fan events so that they are reported correctly.
 - Provides support for the Compaq AlphaServer DS20E.
- Allows the com1_environment variables to be stored in NVRAM.
 On a DS10 platform, resetting console baud rate to anything other than the rate it was running, a system panic occurs at boot.
- Fixes various problems with the driver support for the Powerstorm 4D10T (ELSA Gloria Synergy) graphics board.
- Provides the driver support for the PCI To Ethernet/Graphics Combo Adapter (3X-DEPVD-AA) (also known as the ITI6021E Fast Ethernet NIC 3D Video Combination Adapter, InterServer Combo, or JIB).
- · Adds additional error detection to the FC driver.
- Updates the emx Fiber Channel driver to revision 1.12, adds support for the KGPSA-CA adapter, and also fixes the following problems:
 - In an ASE environment, the driver was not appropriately restoring the link state after a LIP, which typically occurs when the Fiber Channel cable has been unplugged.
 - When connected to the new Pleiades II switches, the switch ports would consume target IDs on the adapter's SCSCI bus.
 - A kernel memory fault in routine emx_handle_els_request.
 - A system hang at boot up caused by infinitely trying to probe the Fiber Channel link.
- Fixes a problem where, on systems with a Powerstorm 4D10T (ELSA Gloria Synergy) graphics board, the graphics were not reset to console mode (the blue screen) when the halt button was pressed.
- Fixes several KZPCC RAID controller problems which in turn provides full support of the product.
- Updates the emx Fiber Channel driver to Revision 1.17, correcting the following problems:
 - If connected to a switch that is part of a cascaded set of switches and is not the primary switch in the fabric, the host will never complete link initialization.
 - Occasionally, the link fails to initialize on the KGPSA-CA at boot.
 - If the cable connection between the switch and KGPSA-CA was unplugged and then replugged, the KGPSA-CA would fail to properly initialize the link and all FC connections would be terminated until the next system reboot.
 - Corrects some boot messages indicating mailbox command failures.
- Fixes a kernel memory fault caused by a streams SMP race condition.

Patch 640.00 continued

- Fixes the following Universal Serial Bus (USB) problems:
 - The USB mouse no longer functions after resetting the Xserver.
 - System panics may occur in error handling after USB device fails a request.
 - The USB device may not deconfigure properly when unplugged from the bus.
 - Problems that will prevent some USB devices from being configured at boot time.
 - A key on a USB keyboard will continue to repeat after being unplugged.
 - USB keyboards may transmit the incorrect keycode for several
- Fixes a system hang in which there is a large number of pending ioctl's on the streams queue.
- Fixes a panic in AdvFS which can have the following error messages:

panic (cpu 1): bs_cow_pg: pin clone err

panic (cpu 1): bs_cow_pg: cannot get blkMap

- Fixes a kernel memory fault caused by a mishandling of multicast addresses on the FDDI interface.
- Fixes a problem most frequently encountered by the ppp daemon /usr/sbin/pppd when the ppp connection is terminated. When run in debug mode, an exiting pppd will log a message similar to the following when the error is encountered:
 - >> May 25 12:29:17 dragon pppd[2525]: ioctl(SIOCDIFADDR): Invalid argument
- Fixes a kernel memory fault and an SMP race condition with the AltaVista Firewall 98 server on a multi-CPU system.
- Fixes a problem when a default IP address and a cluster virtual IP address are interchanged after a network restart. The default interface address is used by all outgoing traffic and the alias address is only usable for the incoming packets.
- Fixes a problem in which the system may panic with the error message "tcp_output REXMT".
- Fixes a problem where RCP commands issued from a Sun Solaris system to Compaq Tru64 UNIX may sometimes fail incorrectly with the error message "Connection reset by peer".
- Fixes a TCP performance problem if the TCP window scale option is turned off when using the HIPPI interface.
- Fixes a system panic:

tcphdr too big

- Consists of changes necessary for the AltaVista Firewall 98 to pass ICSA certification.
- Fixes a problem with packetfilter applications that use IP packets greater than 8K.
- This patch involves virtual mac addressing.

Patch 640.00 continued

- Fixes a problem that caused AdvFS to incorrectly calculate metadata file size for files greater than 4 GB resulting in corruption on read and stat syscalls.
- Fixes a bug such that when fuser -k is issued on a dismounted NFS mount point in which some process is running, a hang will occur.
- Fixes a problem in which an invalid error status is returned from the remove_entry system call.
- Fixes a problem in which the interaction between NFS file systems and Smoothsync causes procprod to read stale data.
- Fixes a kernel memory fault when accessing the vm_map_index hash table.
- Fixes a simple_lock time limit exceeded panic due to an SMP race condition in namecache.
- Fixes a problem that causes corruption in the floating point registers whereby the flag fields nxm_fp_owned are overwritten with 0s.
- Fixes a problem in AdvFS. The system panics with a kernel memory fault.
- Fixes a problem in AdvFS. A system panic occured with the following error message:

panic: del_dealloc_stg(): cant ref bmt page

- · Fixes a kernel memory fault in VMAC code if_addnewaddr().
- Fixes a system hang that could last up to a few minutes with large files when performing synchronous IO requests.
- · Fixes a system panic with the panic string:

psig: catch not set

- Corrects a kernel memory fault caused by rw3vp_cache passing a bad address to _OtsZero().
- Corrects a problem in which the perrmask register on Tsunami systems can be overwritten.
- Fixes a problem where the output of a ps command, the PAGEIN column reports 0 for all processes.
- Fixes a problem in which an application can hang because of an undelivered signal.
- Fixes a problem in Advfs. A panic occurs with the following error message:

lock_read: hierarchy violation

- Fixes a problem where the system appears to hang. A child process is holding a lock too long and preventing other processes from doing work.
- Fixes a problem where, if the size of the message queue was increased, writers to the queue that were blocked would not wake up for processing.

Patch 640.00 continued

- Fixes a problem in which the POSIX interval timer is not resilent to clock slowdown caused either by NTP or by a backwards change of the clock.
- Fixes a system panic that was seen on large configurations under a heavy load situation.
- Provides the latest driver for the PowerStorm 4D10T (ELSA Gloria Synergy, SN-PBXGK-BB) graphics card and the latest graphics driver for the PCI To Ethernet/Graphics Combo Adapter (3X-DEPVD-AA).
- Fixes a problem in AdvFS where putpage_lk/pg_busy deadlock causes hangs in the system.
- Fixes several panics on systems with holes in memory. The error messages are listed below:

panic: put_free_ptepage: invalid pvh state

panic: kernel memory fault

trap: invalid memory read access from kernel mode

panic: not wired

simple_lock: hierarchy violation

- Adds a fix to VMAC functionality when used with NetRAIN.
- Fixes a problem where the following can occur during a system
 - System calls interrupts
 - mpsleep() returns an EINTR error when the panicstr is non-NULL
 - An infinite looping at a very high priority
- Fixes AdvFS inconsistent quota problems and errors similar to the following appearing on the console:

vmunix: chk_bf_quota: group quota underflow

- Fixes a problem with verify. When verify is run on a brand new domain, NFS warnings are displayed even though no NFS related activity is being done.
- Corrects a problem with the incorrect ordering of network interfaces which was resulting in network partitions.
- Fixes a "lock_terminate: lock held" panic when deleting a process group.
- Fixes an "unaligned kernel space access from kernel mode" panic when doing a malloc from kmembucket 26, 896 byte bucket. The faulting virtual address will be the lock signature for thread_deallocate().
- Fixes a kernel memory fault in u_anon_faultpage() when it accesses the backing object for the anonymous page.

Patch 640.00 continued

- Fixes a problem where a root user was not allowed to check file access on behalf of a user without completely becoming the user.
 The functionality is needed by the ASU (Advanced Server for UNIX) product.
- Fixes a panic in in_pcbfree() associated with ASE service failover.
- Fixes a file system panic which has the following error message: syscall: complex lock owned
- Fixes an AdvFS problem which caused the system to crash with a kernel memory fault.
- Includes UFS delayed metadata mount option that fixes metadata intensive application performance.
- Fixes a kernel memory fault seen under certain conditions when setting a thread's priority.
- Fixes a race condition in the UBC code where a lookup is done on a page being invalidated (freed).
- Fixes a race condition involving signals and threads that only happens on multiprocessor systems.
- · Fixes a problem with a kernel memory fault in AdvFS.
- Fixes a problem where the operating system only looks in slot 0 for the primary CPU.
- Corrects a KZPCC lock problem that is seen when a kernel is run
 with lockmode set to four. This patch also resolves a timing issue
 which prohibited the KZPCC product from being seen during boot
 on EV67 platforms.
- Fixes a kernel memory fault caused by either one of the following conditions:
 - On EV6 platforms, when the debugger is used to view the OT_DEVMAP object mapping memory in I/O space that is mapped to a user process.
 - When routine pmap_coproc_exit_notify() modifies the pmaps' coproc_tbi function to be 0, a null pointer, while it is being checked by routine pmap_remove_all().
- Fixes a problem in which operations on NFS files can hang indefinitely.
- Updates the emx Fiber Channel driver to revision 1.21 which corrects a Data Error that is seen when running with the latest Emulex firmware. This error corrupts data when reading from the disk.
- Fixes a problem in which an invalid PCI entry in sysconfigtab can cause the system to be unbootable.
- Fixes a problem in which a PCI bridge-based boot device may fail to configure on large I/O systems.

Patch 640.00 continued

- · Fixes a problem where genvmunix does not boot on a system with an Atalla AXL200 card installed.
- Fixes several problems specific to AlphaServer 1200 and AlphaServer 4100 systems.
 - The user.log file has the following message: redundant power supply failure
 - The messages file has the following intermittent messages:

ERROR: i2c_read_temp: environmental monitoring error

ERROR: i2c_read_fail_reg: environmental monitoring error

ERROR: i2c_read_func_reg: environmental monitoring error

Systems were shutting themselves down displaying the following message:

System has reached a high temperature condition. Possible problem source: Clogged air filter or high ambient room temperature.

- Modification to pci resource management to allow support behind pci bridges for the AXL200 card.
- Fixes a system hang problem due to a bug in the NFS write gathering code. The code does not fully synch all writes.
- Fixes a problem where applications on V4.0F systems can hang, looping in readdirplus().
- Fixes a problem in which an NFS system using a TCP connection can crash.
- Fixes various performance problems with an upgrade to the Gigabit Ethernet driver Version 1.0.12.

Patch 640.00 continued

- Fixes a problem with relocating an TCR/ASE NFS service when one or many clients have the service mounted over TCP.
- Corrects a problem which could cause the system to spend excessive time in the internet checksum routine, resulting in a degradation of system performance.
- Fixes reply values for NFS writes which were causing protocol violations.
- Fixes a problem in AdvFS in which a system that had already domain panic'ed results in a system panic.
- Provides support for the DEGPA-TA (1000BaseT) Gigabit Ethernet device.
- Fixes a problem that caused an incorrect bcache size to be returned to the kernel from the HWRPB. This problem occurred on Professional Workstation 900 and 1000 systems and AlphaServer DS10, DS20, DS20E, ES40, GS80, GS160, and GS320 systems.
- Fixes an AdvFS kernel memory fault caused by a race condition between migrate and chfile -L in bfflush_start.
- Provides the device driver support for 3DLabs Oxygen VX1 graphics adapter.
- Fixes a panic in the UFS filesystem which has the following error message:

blkfree: freeing free block

- Provides support for the DE600/DE602 10/100 Ethernet adapters and fixes the following problems in the driver shipped as part of the NHD kit:
 - A machine check that may occur shortly after boot or when receiving large amounts of data.
 - The primary CPU may appear hung on networks where switches send "Flow Control Pause" frames if they become overloaded.
 - Transmit timeout messages appearing in the console log due to the driver timing out a frame.
- Fixes a panic in in_pcbfree() when NFS is implemented over TCP.
- Fixes a problem with AdvFS. An AdvFS domain becomes inaccessible when using the mount -d option.

Patch 640.00 continued

- Corrects a kernel problem which causes ping(8) to hang when using the -d flag.
- Fixes a problem with AdvFS in which a hang occurs due to a deadlock between bsbuf.state and bmt extent map lock.
- Fixes a problem in AdvFS. The following error messages can occur:

simple_lock: uninitialized lock

kernel memory fault: simple_lock: minimum spl violation

- Corrects a problem when a network interface is configured using a CIDR bitmask and lies in a certain address range; it could be unreachable by users on the local system and remote systems that choose not to use the routing table, but simply transmit on an interface.
- Corrects a problem where there is a potential for a system panic in routine sbflush() if there is an attempt to flush a socket buffer while it is locked by another thread.
- Fixes a problem with AdvFS where all processes are waiting for buffers causing the system to hang.
- Fixes a hang or simple_lock_state_violation/simple_lock_fault panic in biodone.
- This patch fixes a panic in AdvFS that has the following error message:

ftx_fail_2: dirty page not allowed

Fixes two panics that have the following error messages:

simple_lock: time limit exceeded

simple_lock: lock already owned by cpu

Fixes a problem in AdvFS where user data may be lost when a clone file is migrated.

Patch 640.00 continued

- Fixes a problem where NFS does not update mtime and atime for special files and named pipes. Additionally, it fixes a problem that can cause an NFS client application to hang, or causes a "lock already owned by thread" panic when lockmode=4.
- Fixes a problem where incorrect NFS client locking caused a KFM panic.
- Fixes a problem where NFS clients may hang in the uninterruptable state.
- Fixes a restart detection problem with the proplistd daemon. Prior to this fix, when mounting a relocated ASE NFS service with property lists, clients did not detect that the proplistd RPC port number had changed. Clients continued to use the proplistd RPC port number of the old ASE cluster member.
- Prevents a possible NFS over TCP hang. NFS TCP threads will be blocked in sosbwait() causing the system to appear to be hung.
- Addresses two problems with the ee driver for DE60x Ethernet cards. These problems affect all Tru64 systems containing ee cards.
 - Fixes a race condition where the card could stop receiving packets from the network under rare circumstances.
 - Fixes the lan_config user options -x and -s.
- Fixes a problem when using multiple subnets on a network interface; APR request packets sent by the system will contain the IP alias address in the sender field when that alias is in the same subnet as the requested IP address.
- Fixes a problem when applications make IOCTL calls using an IP alias address on a network interface.
- Corrects a problem in which a single application's creating and removing of files repeatedly in the absence of other applications working on the same fileset can cause poor update daemon performance due to a flawed kernel hashing algorithm.
- Fixes panics which can occur if a signal is sent to a multi-threaded task in which one or more threads are calling exit() or exec().
- Fixes a problem where the setgid bit of a directory was not being set when created, if its parent directory has the setgid bit set.
- Fixes hangs in AdvFS fileset operations such as clone creation and deletion when I/O errors or device full conditions resulted in the operation being undone.
- Fixes a problem in which the system may panic with the panic string "Unaligned kernel space access from kernel mode".
- Fixes a kernel memory fault from ufs_mount().

Patch 640.00 continued

- Corrects a simple lock timeout seen when dealing with NFS loopback mounted file systems with large amount of dirty pages.
- Fixes an unaligned access panic which occurs in malloc() in V4.0F systems, while allocating memory from the 512 byte memory bucket. It can occur on any type of filesystem.
- Provides support for activating temporary data logging on a mount point.
- Fixes a timing window where flushing data to disk can be incomplete when a system is going down, if more than one thread calls reboot() without first going through shutdown, /sbin/reboot, or /sbin/halt.
- Addresses multiple issues for the KZPCC family of RAID Array 2000 (RA2000) controllers.
 - Errors seen when concurrent opens are issued to separate logical partitions on the same logical device.
 - Change to the preferred chunk size from 16 KB to 64 KB which may increase data transfer rates.
- Fixes a problem in which the wrong status was returned from EEROM read.
- Prevents a system panic from occurring while using ADVFS.
- Fixes a problem with the driver for Gigabit Ethernet adapters (DEGPA-FA and DEGPA-TA) which prevented its use in a NetRAIN (Redundant Array of Independent Network Adapters)
- Fixes a system hang caused by netisr queue corruption due to a race condition that is primarily encountered by third party drivers and layered products that call schednetisr_nospl().
- Modifies advfs kernel code and several utilities. AdvFS will no longer panic with the following error:

ADVFS EXCEPTION: panic cpu(0): bad frag free list

The code is modified so that during frag allocation when AdvFS determines that the frag group header's free list has been corrupted, it stops using it and marks it BAD. It is then removed from the free list so no more allocations can take place AND no deallocations are performed. The verify, shfragbf and vfragpg programs are modified to report BAD frag groups.

Corrects an AdvFS panic which can occur during a rmfset operation, causing the following panic string:

rbf_delete_int: can't find bf attributes

- Corrects a problem where a directory entry may be attempted to be changed to "." and the code checks for this and prevents it from happening.
- Fixes a lock hierarchy violation in AdvFs.
- Increases the efficiency of the tcp_timers.

Patch 640.00 continued

- Fixes inaccuracy problems when using setrlimit/getrlimit with a threaded application.
- · Fixes a problem in which rmvol would hang in a wait state.
- Fixes a hang in the UFS filesystem.
- Fixes two problems with the consvar command:
 - Fixes consvar command problem with setting a boot device to a tape device.
 - Fixes consvar -g command to actually show the console settings as intended.
- Fixes a memory leak when named pipes (FIFOs) are used.
- Fixes a potential problem flushing data to disk when using data logging with sparse files.
- Fixes a problem where threads can hang in x_load_inmem_xtnt_map().
- Fixes a problem where cascaded switches can hang the system at failover time.
- A potential security vulnerability has been discovered where, under certain circumstances, system integrity may be compromised. This may be in the form of improper file or privilege management. Compaq has corrected this potential vulnerability.
- CDFS media burned in 2001 shows the wrong dates.
- Fixes a "u_anon_free: page busy" panic.
- Fixes a problem where threads can hang while renaming files on nfs mounted filesystems.
- Fixes a "simple_unlock: lock not owned by cpu" panic in the biodone routine.
- Provides several fixes including:
 - Signal parent process to enable user notification of mount failure.
 - Return functionality to accept disk-type from user.
 - Exit if overlap detected and not being run interactively.
 - Do not do check_usage for -N option or mfs.
 - Move common variable declarations to header file.
 - Adjust fssize and references to it to handle larger file systems.
- Fixes a kernel memory fault which occurs while using the tablet instead of the mouse.
- Fixes a panic in AdvFS which has the following error message:

panic: Unaligned kernel space access from kernel mode

 Fixes an AdvFS hang that is caused by a thread waiting for flushCv notification and is holding resources that other threads want. This type of hang has been experienced when shutting the system down.

Patch 642.00 OSF440-544B

Patch: Support for activating temporary data logging **State:** Supersedes patch OSF440-296 (361.00)

This patch fixes a problem in which the chille utility returns an incorrect error code. This patch provides support for activating temporary data logging on a mount point.

Patch 644.00 OSF440-585B Patch: Modifies AdvFS kernel code

State: Supersedes patches OSF440-040 (35.00), OSF440-183 (240.00), OSF440-330 (384.00)

This patch corrects the following:

- Allows the /sbin/advfs/verify utility to detect loops in the list of free frags kept in the frags file.
- Avoids corruption of a filesystem when verify runs with -r and -f flags on an active domain. Verify returns usage message when -r flag is used with either -f or -d.
- Fixes the following /sbin/advfs/verify command problems:
 - Verify fails to complete on a large number of files.
 - Verify will core dump when an offset into mountd[] array that is used to pull out the fileset name is corrupted.
 - Verify incorrectly reports errors on BMT's that have multiple extent records for domains created with the mkfdmn -p switch.
 - Verify fails when lseeking on very large domains.
- Modifies AdvFS kernel code and several utilities.
- AdvFS will no longer panic with the following error:

ADVFS EXCEPTION: panic cpu(0): bad frag free list

The code is modified so that during frag allocation when advfs determines that the frag group header's free list has been corrupted, it stops using it and marks it BAD. It is then removed from the free list so no more allocations can take place AND no deallocations are performed. The verify, shfragbf and vfragpg programs are modified to report BAD frag groups.

Patch 646.00 OSF440DX-023 Patch: Updates Netscape Communicator to Version 4.76

State: New

This patch updates Netscape Communicator to Version 4.76 to fix missing default MIME types in Netscape Communicator Version 4.75.

Patch 651.00 OSF440-495 Patch: Security (SSRT0689U, SSRT1-19U)

State: Supersedes patches OSF440-102 (79.00), OSF440-151 (125.00), OSF440-035 (138.00), OSF440-093 (172.00), OSF440-115 (91.00), OSF440-098 (177.00), OSF440-094 (173.00), OSF440-193 (247.00), OSF440-223 (266.00), OSF440-357 (408.00), OSF440-054A (48.00), OSF440-388 (438.00), OSF440-111 (87.00), OSF440-411A (457.00), OSF440-431 (508.00), OSF440-423 (509.00), OSF440-479 (511.00), OSF440-510 (647.00), OSF440-535 (648.00), OSF440-542 (649.00)

- Modifies the strftime() function to make the %V format specifier return the correct week.
- Fixes a problem of password error messages not being displayed during installation of the security subsystem.
- The routines wprintf(), swprint(), and fwprintf() do not handle the S format correctly. Instead of treating the data as logical characters, they treat data as bytes.
- Fixes problems with rsh(1), rlogin(1), and rcp(1) if netgroup names are defined with uppercase letters.
- Fixes a problem with portmap by allowing RPC select() timeouts to occur when interrupted by signals.
- · Fixes and enhances the quotacheck and fsck commands.
- Fixes a problem in which the fsck utility may be unable to repair a UFS filesystem.
- Fixes a problem in which ufs_fsck can get blocked while attempting to flush NFS buffers for a service that has become suspended.
- Fixes a problem that was causing the csh globbing function to be extremely slow when accessing file information on NFS, AFS, or VMSTM™ file systems.
- Increases the length of the user names for rsh and rexec to allow for NT interoperabilty.
- Fixes a problem where gmtime() was erroneously setting the tzname[0] array.
- Fixes problems in the DECthreads library for Tru64 UNIX.
 Included in this patch are changes to support Ladebug enhancements and a bug fix for applications which employ SCS threads of different priorities.
- Fixes bugs in the DECthreads library that would affect threaded applications running on Tru64 UNIX V4.0F. The changes are related to synchronous signal processing and thread scheduling.
- Addresses performance and scalibility issues for highly contended threaded applications running on EV6 SMP machines.
- Fixes a problem in libc that affects debugger tracebacks of code containing split procedures.
- Adds functionality to terminate the resulting string from calls to swprintf().
- Fixes a problem for those applications that assume initial allocations of memory from the C run-time library's malloc() function will return only zero-filled memory.
- A potential security vulnerability has been discovered where, under certain circumstances, system integrity may be compromised. This may be in the form of improper file or privilege management. Compaq has corrected this potential vulnerability.

Patch 651.00 continued

- Fixes four problems for threaded applications on Tru64 UNIX
 - _pthreads_legacy_init_routine shows up as an unresolved symbol.
 - Programs linked -taso experienced truncated address values resulting in SEGV or data corruption errors.
 - A memory leak when the pthread_attr_setname_np function is
 - pthread_setname_np occasionally returning an EINVAL error.
- Fixes a bug where quotacheck -v <filestystem> will report that it has fixed some quotas. If you keep running the command, it will keep reporting the exact same fixes.

Patch 653.00 OSF440-526

Patch: Fix for grep -w command

State: Supersedes patches OSF440-378 (428.00), OSF440-381 (431.00), OSF440-432 (517.00)

- Corrects a problem with the fgrep command. When it is used with the -s flag, all output is suppressed.
- Fixes a limitation problem with the grep and fgrep commands. If the line length is too long, grep displays a "wordlist too large" error message and fgrep displays "input too long" error message.
- Fixes the following two problems:
 - fgrep limits are too small.
 - fgrep displays data files verbatim if pattern_file has blank
- Fixes a problem in which the grep command with the -w switch does not work as documented.

Patch 659.00 OSF440-552 Patch: ksh problem occurs in multi-byte Asial locales

State: Supersedes patches OSF440-017 (15.00), OSF440-026 (23.00), OSF440-027 (24.00), OSF440-028 (25.00), OSF440-146 (120.00), OSF440-055 (142.00), OSF440-066 (145.00), OSF440-077 (156.00), OSF440-096 (175.00), OSF440-318 (376.00), OSF440-359 (410.00), OSF440-392 (440.00), OSF440-464 (521.00), OSF440-390 (654.00), OSF440-532 (655.00), OSF440-551 (656.00), OSF440-498 (657.00)

This patch corrects the following:

- Fixes a problem with /usr/bin/ksh and the named-pipe (FIFO) communication that is used by applications.
- Corrects a problem that was causing ksh to core dump in vi editing mode. ksh was core dumping intermittently when using "." to repeat a command.
- ksh does a segmentation fault and core dumps when displaying a here-document.
- Fixes problems in ksh, file, tail, nawk, awk, and pax:
 - Unexpected logouts and terminal hangups occur when using the /bin/su command and /bin/ksh as a login shell.
 - The file command gives incorrect output concerning WAV audio files.
 - The tail command gives erroneous output when used with both the -n and -r flags.
 - The maximum number of fields per record was changed from 99 to 199 for the awk command.
 - The tar/pax program did not always read the last tape record of an archive. This caused confusion for scripts that were reading a series of archives on the no-rewind device.
- Fixes a problem in ksh which required two SIGTERM signals to be sent to the process when it exec'ed.
- Corrects a problem that may cause ksh to core dump when displaying a large here-document in a ksh script.
- Fixes a problem that caused incorrect file dates to be restored when pax was used to copy files.

The problem occurred in the following cases:

- If the file was a nonempty directory.
- If the file was the target of another symbolic link.
- Fixes a core dump from ksh.
- Fixes a problem with the Korn shell where data loss occurs when commands are piped together.
- Fixes a problem in ksh in which a space after the -p switch would cause the command to fail.
- Fixes a problem in ksh. When the current working directory is / and the command cd .. is entered, the following error message is displayed:

ksh: ..: bad directory

- · Fixes a cpio hanging problem in the Japanese locales.
- Fixes a problem with the tar command. Corruption occurs when restoring a file system that contains more than two hard links to a file.
- Fixes a problem where the tar -F (Fasttar) option ignores files named err" but doesn not ignore files named errs and directories named SCCS and RCS.

Patch 659.00 continued

- Fixes a possible handling problem with multibyte character boundary conditions in ksh script processing.
- The directory option was similarly affected. In this case the information for the specified file was not reported.
- Fixes a problem with the tar and pax programs. These programs incorrectly append files to an existing archive and cause the file to become corrupt.
- Fixes two ksh problems that occur in multi-byte Asian locales.

Patch 661.00 OSF440-467

Patch: Security (SSRT0636U)

State: Supersedes patches OSF440-019 (17.00), OSF440-329 (383.00), OSF440-444 (534.00)

- Fixes a problem in which a BIND server may find that named will place a warning message in the daemon.log that was not previously seen.
- Fixes a problem in which a BIND server writes files to the /etc/namedb directory instead of the /var/tmp directory.
- A potential security vulnerability has been discovered where, under certain circumstances, system integrity may be compromised. This may be in the form of improper file or privilege management. Compaq has corrected this potential vulnerability. This patch fixes a problem where named could possibly core dump when printing an informational message to syslog.
- Fixes a problem of named producing a core file when named is started and the named.boot file has more than 32767 zones specified.

Patch 664.00 OSF440-528 **Patch:** Upgrades sys_check utility to v120

State: Supersedes patches OSF440-154 (128.00), OSF440-258 (293.00), OSF440-275 (309.00), OSF440-478 (522.00), OSF440-484 (524.00), OSF440-563 (662.00)

- Provides bug fixes to the sys_check utility and updates the sys_check to version 114.
- Provides the following changes to the sys_check utility:
 - Fixes the ra200info tool from core dumping.
 - Adds the sysconf program.
- Fixes the following two problems with the collect information tool used by the sys_check utility:
 - A security hole where a user can become root.
 - collect cannot start at boot time due to incorrectly handling SIGHUP signal.
- Upgrades sys_check utility to version 119.1 and provides the following changes:
 - Two NFS problems.
 - Fixes the ra200info tool from core dumping.
 - Utilizes Compaq Analyze when available.
 - Utilizes the new storage cliscript tool in place of hsxterm.
 - Updates the ASU section.
- Fixes several problems with the collect command, and adds sysloging when collect suspends, resumes, or receives a signal.
- Fixes errors generated by syscheck when NFS is not configured.
- Upgrades sys_check to V120.

Patch 666.00 OSF440-509

Patch: Miscellaneous print command fixes

State: Supersedes patches OSF440-236 (275.00), OSF440-254 (289.00), OSF440-333 (386.00), OSF440-485 (538.00), OSF440-452 (540.00)

This patch corrects the following:

- When printing jobs, a timeout can occur after five minutes which causes some large print jobs to stop, then resume printing from the beginning of the print job.
- When slave lpd daemons try to process jobs on the print queue, some of them can fail to obtain a lock on the lock file, and exit with an error.
- Print jobs will print out twice.
- A remote print job may fail to print, with the error message:

lstat/open failed for dfA... no such file or directory

- If a print job is printing, and the connection to the remote printer is lost, the print job does not resume printing after the connection is restored.
- Sometimes, as sequence numbers wrap around from 999 to 000, job 000 gets submitted before, and prints before, job 999.
- lpstat -u output is incorrect.
- When using the I18N ya option, the queue daemon filters will terminate after 32 jobs.
- Under certain circumstances, print jobs are terminated when printing to certain printers that are connected to a DECserver through TCP/IP.
- When lpd reads any data from the printer that has not been read, for local and remote connections, the read-backs for remote connections cause an additional 2-second time out which may cause a job-submit failure on the job-number wraparound.
- Corrects a problem in which, under certain conditions, unnecessary error messages are written to the lpr.log file.
- A user is unable to delete a print job from a remote system with a hostname greater than 32 characters because the hostname was truncated.
- When a TCP/IP connection fails, the retry algorithm would take longer to print jobs due to a long retry interval.
- A timing hole during lpd last-job completion and shutdown needed to be closed.
- It was not possible to print to the lpd queue using Windows 2000.
- Introduces the JJ /etc/printcap parameter, which allows the user to choose either one TCP/IP connection for all jobs in the print queue (JJ=1), or a TCP/IP connection for each job in the print queue (JJ=0). It also closes a timing hole that existed when lpd was shutting down.
- Fixes a problem in which lpd hangs when printing to advanced server queues (using /dev/null).

Patch 668.00 OSF440-513

Patch: ATM setup script fails when configuring ELAN

State: New

This patch fixes a problem of the ATM setup script failing when configuring an elan if the lane subsystem is not loaded.

Table 2–2: Summary of Base Operating System Patches (cont.)

Patch 670.00 OSF440-572

Patch: Incorrect heartbeat timer in memory channel driver **State:** Supersedes patches OSF440-118 (94.00), OSF440-403 (451.00) This patch corrects the following:

Fixes an incorrect heartbeat timer within the memory channel driver which caused rail failures to be incorrectly reported on memory channel Version 2 cards. With the heartbeat timer set too short, the system can be erroneously led to believe a hardware failure has occurred. Messages of the form "rmerror_int: ..." are output to the messages file containing an error_type which has bit 29 set in error_type (heartbeat timeout). The binary error log will also have this data. Typically, the error_type data will be 0xe00000000. The messages are followed by the system hanging or panicing. When panicking, the following message is produced:

panic (cpu 0): rm_failover_if_necessary, both rails bad

A real hardware failure produces the same symptoms and stack trace. For example, having an error_type of 0xe00000002 indicates a write transmit hardware fatal failure.

- Fixes a problem where an MC1 or 1.5 will not configure with an ev6 8x00. It also improves error handling with MC 2 in a Virtual Hub.
- Fixes a problem in the memory channel driver which could result in panics with rm - inconsistent local spinlock structures being logged.

Patch 672.00 OSF440X11-041A

Patch: Fix for pixel problem for CDE

State: New

This patch fixes the problem of erroneous pixels left behind when dragging CDE application manager icons on the desktop.

Patch 674.00 OSF440-547

Patch: Fix for various vdump problems

State: Supersedes patches OSF440-048 (42.00), OSF440-237 (276.00), OSF440-404 (452.00), OSF440-089 (167.00), OSF440-338 (588.00)

This patch corrects the following:

- The command was slow to complete when a partial restore operation was requested.
- The command failed to ignore extended attribute records for the files which were not requested for a vrestore operation.
- Fixes problem with vrestore where vrestore fails to restore certain files and directories having ACLs from a compressed vdump saveset, reporting:

vrestore: error setting extended attributes 22

- A previous patch caused incomplete restores.
- A warning message is displayed when the path for the first file in a group of hardlinks is created without using original protection codes and property lists.
- A warning message is displayed and vrestore aborts if it fails to malloc space for a property list.
- A message which had been inserted at the end of the message file had the wrong message category (could cause messaging confusion).
- An uninitialized variable in the code that restores property lists could cause malloc failures, memory faults, "error setting extended attributes", and infinite loops using the -l option.
- Corrupted property list information could cause an infinite loop.
- Fixes a problem where the vdump program would dump core with the following message:

nnnn Resources lost(coredump)

- Fixes a problem where the vdump command will sometimes store symbolic link files as directories in the vdump archive.
- Fixes the following problems with the vdump command:
 - Fixes a problem where the vdump command will sometimes store symbolic link files as directories in the vdump archive.
 - Failed to flag compressed extended attributes records that are split across a vdump BLOCK boundary.
 - Overrides the -D option when source path describes a root fileset Note: If you want to backup quota files, you must not use the -D option.
 - Corrects "Rewinding" message to avoid a segfault with Internationalized messages.

Fixes the following problems with the vrestore command:

- Fails to properly handle extended attributes records in compressed archives. This results in malloc failures, proplist inconsistencies, program abort, program crashes due to segfault or invalid memory access, and the display of the error message "error setting extended attributes".
- Fails to set extended attributes due to confusion over selective restore of the file or directory associated. Also results in the display of the error message "error setting extended attributes".

Patch 674.00 continued	 Selective restore of hardlinked files is incomplete when they exist in different directories (fails to create directory for second occurrence of file with same inode number).
	 The -Q option is added to vrestore to allow the user to request ignoring the quota files (thus avoiding the time it takes to process them).
Patch 676.00	Patch: Fix for newgrp command
OSF440-516	State: New This patch corrects the problem where newgrp(1) fails if the file /etc/group contains multiple lines for one group.
Patch 678.00 OSF440-499	Patch: Fix for os_mibs core dump State: New
	This change fixes a problem wherein os_mibs would core dump.
Patch 680.00 OSF440-548A	Patch: libots3 shared run-time library fix State: Supersedes patch OSF440-150A (124.00) This patch corrects the following:
	Fixes the following problem in the libots3 run-time library:
	 The failure to check the return status after certain system calls caused a problem in the libots3 run-time library. The libots3 run-time library supports OpenMP parallel applications.
	 Fixes the following problem in the parallel processing support library (libots3):
	 A problem in the parallel processing support library that caused incorrect run-time results for an OpenMP program.
Patch 682.00 OSF440-548B	Patch: libots3 static run-time library fix State: Supersedes patch OSF440-150B (204.00) This patch corrects the following:
	Fixes the following problem in the libots3 run-time library:
	 The failure to check the return status after certain system calls caused a problem in the libots3 run-time library. The libots3 run-time library supports OpenMP parallel applications.
	 Fixes the following problem in the parallel processing support library (libots3):
	 A problem in the parallel processing support library that caused incorrect run-time results for an OpenMP program.
Patch 684.00	Patch: Fixes automount handling of nogrpid option
OSF440-537	State: Supersedes patch OSF440-024 (22.00), OSF440-377 (427.00) This patch corrects the following:
	 Fixes a problem in which the automount daemon hangs when invoked by the rsh command.
	 Prevents the message "nfscast: select: Invalid argument" message from appearing in the daemon.log when the server is not available. It also changes the "trymany: servers not responding: RPC: Unable to receive " message to an informational vs. error message.
	 Fixes the automount handling of the nogrpid option.
Patch 686.00 OSF440-496	Patch: Fixes a problem in rpc.lockd State: New This patch fixes a problem in rpc.lockd where the FCNTL () function

Table 2–2: Summary of Base Operating System Patches (cont.)

Patch 688.00 OSF440-565

Patch: Fixes problems with dbx kernel debug option **State:** Supersedes patches OSF440-101 (78.00), OSF440-391 (439.00) This patch corrects the following:

- Fixes a problem in viewing a variable subrange parameter from a Pascal module while using dbx.
- Fixes three problems in dbx:
 - dbx stack trace is incomplete.
 - Assignment to a variable would fail after viewing a non-local symbol.
 - The use of vfork would raise a signal 66.
- Fixes problems with the dbx kernel debug option when used on kernel core files from wildfire and other large memory systems.

Patch 690.00

Patch: Fix for dtpad

OSF440CDE-028A State: Supersedes patch OSF440CDE-009A (186.00)

- Fixes a problem where the Account Manager application, dxaccounts, gets a "BadPixmap" error when selecting an account after the View Preferences Display Icons By Name option has been selected.
- Fixes a problem where, if dtpad cannot allocate enough memory, it will exit and leave a zero-length file in place of the file being edited.

Patch 695.00 OSF440-533

Patch: linker erroneously reports unresolved symbol errors **State:** Supersedes patches OSF440-139 (113.00), OSF440-230 (207.00), OSF440-231 (208.00), OSF440-195 (249.00), OSF440-350 (401.00), OSF440-376 (580.00), OSF440-475 (582.00), OSF440-616 (691.00), OSF440-527 (692.00), OSF440-539 (693.00)

This patch corrects the following:

- Fixes a problem where the linker (ld) would insert incorrect values for the symbols etext and _etext when building kernels larger than 4 MB.
- This patch is needed to support the NHD2 (New Hardware Delivery Two) release. The NHD2 installation process modifies the system's linker and the osf_boot file. This patch preserves the modifications that NHD2 makes to the linker and the osf_boot file.
- Fixes a problem where the linker (ld) could not read arguments longer than 1024 characters in input files. This also adds proper support for line continuation characters.
- Addresses the failure of osf_boot to link in foreign kits with the following message:

osf_boot: Not enough space to add '..... messages

- Fixes a linker problem where including a shared library on a link line twice with another library in between caused unresolved symbols in some cases.
- Fixes a problem in which the bootlink can fail on AlphaStations 600, 600A, and 500/400.
- Fixes a potential optimization problem with the linker (/bin/ld).
- Fixes two errors that occur when using the -f switch with the linker (ld):
 - Using the -f switch produces link errors.
 - Any unsupported switch beginning with -f gets interpreted to mean -f.
- Fixes a problem where the linker defined symbol _fpdata would end up being undefined if it was referenced by a program but not used by the linker.
- Fixes two problems in the linker where it would erronously report "multiply defined symbol" errors or "unresolved symbol" errors:
 - Modifies the linker's symbol resolution to enable it to recognize when a reference to a symbol defined in a shared library is replaced by a symbol defined in an object file or archive.
 - Modifies the linker to cause it to re-scan shared libraries before reporting unresolved symbols.

Patch 697.00 OSF440-555 **Patch:** Fixes DS10/DS20 performance problems **State:** Supersedes patch OSF440-145 (119.00)

- Fixes a intermittent hang occurring in the i2c code. This hang is most commonly seen on the DS10 workstation.
- Fixes DS10/DS20 performance problems introduced with the i2c driver by using thread blocking, rather than event_meout() and DELAY().

Table 2–2: Summary of Base Operating System Patches (cont.)		
Patch 699.00 OSF440-545	Patch: inetd may terminate without notice State: Supersedes patch OSF440-080 (159.00) This patch corrects the following:	
	 Fixes a problem in which a system can hang when inetd tries to start a daemon listed in inetd.conf which is not installed on the system. This can occur when a user attempts to telnet to the port reserved for the nonexistent daemon. 	
	 Corrects a problem with inetd which could result in its termination without notice and without a core file. 	
Patch 701.00 OSF440-529	Patch: vi core dumps when it finds invalid syntax State: Supersedes patches OSF440-053 (47.00), OSF440-334 (387.00) This patch corrects the following:	
	 Fixes a problem where vi puts the server port into PASSALL MODE (where XON/XOFF is no longer effective). This creates garbage in the file. 	
	 Fixes the error handling when invalid multibyte sequences are encountered in the more, ex, and vi commands. 	
	 Fixes a problem in which the vi editor core dumps when it finds invalid syntax during a substitute operation. 	
Patch 703.00 OSF440-566	Patch: binlogd overwrites adjacent header fields State: New	
	This patch fixes a problem in binlogd which overwrites adjacent header fields in an error record if the system's hostname is longer than 12 characters.	
Patch 705.00	Patch: fixso command may cause segmentation fault	
OSF440-506	State: New	
	This patch fixes a problem with the /usr/ucb/fixso command that can cause a segmentation fault.	
Patch 707.00	Patch: Fix for bindsetup problems	
OSF440-511	State: New	
	This patch fixes several problems when bindsetup is used to change hostnames.	

Table 2-2: Summary of Base Operating System Patches (cont.)

Patch 709.00	
OSF440X11-038	R

Patch: Fixes memory leak in the X server

State: Supersedes patches OSF440X11-004 (64.00), OSF440X11-007 (74.00), OSF440X11-009 (199.00), OSF440X11-015 (200.00), OSF440X11-016 (220.00), OSF440X11-022 (352.00), OSF440X11-029 (359.00)

This patch corrects the following:

- Fixes a problem where, on systems with a Powerstorm 4D10T (ELSA Gloria Synergy) graphics board, sometimes the graphics board was not initialized properly and failed to work on power-up or when the X server was restarted.
- Fixes a problem where, on systems with a Powerstorm 4D10T (ELSA Gloria Synergy) graphics board, sometimes the X server does not draw lines correctly.
- Provides the X server support for the PCI To Ethernet/Graphics Combo Adapter (3X-DEPVD-AA) (also known as the ITI6021E Fast Ethernet NIC 3D Video Combination Adapter, InterServer Combo, or JIB).
- Fixes a problem where, on systems with a Powerstorm 4D10T (ELSA Gloria Synergy) graphics board, sometimes the X server did not draw text correctly.
- Fixes a problem where on systems with a PowerStorm 4D10T (ELSA Gloria Synergy, SN-PBXGK-BB) graphics card or a PCI To Ethernet/Graphics Combo Adapter (3X-DEPVD-AA), sometimes lines and images are not drawn correctly in scrolled windows.
- Fixes synchronization and drawing problems in the X server for the PowerStorm 4D10T (ELSA GLoria Synergy, SN-PBXGK-BB) graphics card.
- Fixes a memory leak in the X server on systems with a PowerStorm 4D10T (ELSA GLoria Synergy, SN-PBXGK-BB) graphics card that could occur when a client repeatedly created and destroyed buffers for the X Window System Multibuffering Extension (XmbufCreateBuffers/XmbufDestroyBuffers).

Patch 711.00 OSF440X11-039

Patch: Fixes a memory leak in the libVX11 library

State: New

This patch fixes a memory leak in the libVX11 library used by X applications where freeing a GC would not free all its memory. This problem is most likely to occur on systems with a Catetes graphics card (4D40T, 4D50T, 4D60T, or 4D51T).

Patch 713.00 OSF440X11-041B

Patch: Fix for erroneous pixels

State: Supersedes patch OSF440X11-035 (577.00)

- Provides the Xserver library for the new 3DLabs OXYGEN VX1 PCI graphcis card.
- Fixes the problem of erroneous pixels left behind when dragging CDE application manager icons on the desktop.

Patch 716.00 OSF440-568

Patch: Fixes simple lock timeout on EV6 systems

State: Supersedes patches OSF440-062 (56.00), OSF440-119 (95.00), OSF440-129 (103.00), OSF440-072 (151.00), OSF440-235 (274.00), OSF440-386 (436.00), OSF440-561 (714.00)

This patch corrects the following:

- Fixes a problem in which a system with a KZPCA host bus adapter may hang when the SCSI bus is reset.
- Excessive I/O command timeouts when using KZPCM on CLIPPERs causing disk I/O to be retried and fatal tape I/O errors. Additionally the ITPSA driver now supports the KZPCM, 8951U, and 8952U adapters. Support has also been added to identify hardware in the event log.
- Fixes the following problems related to the ITPSA driver that supports the KZPCM adapter:
 - A panic, machine check, or hang can occur when aborting an I/O due to a command timeout or aborting an application program with pending I/Os.
 - Errors can occur while the system is processing a SCSI bus or SCSI bus device reset request that is issued from the class driver.
 - On the 8951U and 8952U adapters, SCSI bus resets are lost when these adapters are connected to single-ended drives.
 - A panic can occur during boot when lockmode is set to 4.
- Fixes a problem with the ITPSA driver for KZPCM and KZPCA devices, which resulted in a synchronization problem, causing the SCSI bus to hang.
- Fixes the following ITPSA driver problems:
 - The chip interrupt register fields in error log are incorrect.
 - Lessens the opportunity of aborts being issued for an already completed I/O.
 - A kernel memory fault panic caused by a SWS data structure being released twice.
 - A simple lock timeout panic. It was possible for a bus reset to be generated before the previous bus reset was processed, causing excessive processing within the ISR.
 - The driver negotiated for ULTRA2 speed when it was attached to a single-ended bus.
 - The system will panic in itpsa_allocReq() on boot when lockmode=4 is set.
 - Fixes a problem with some slower tape devices serviced by the ITPSA driver by lengthening the timeout value used.
 - Fixes a problem that can cause a simple lock timeout or a kernel memory fault on EV6 systems using the ITPSA driver.

Patch 718.00 OSF440DX-022 Patch: dop cannot find application names containing period State: New

This patch fixes a problem in which dop (division of privileges) cannot find application names which contain a "." (dot) in them. For example, a name such as sysmon.csh.

Patch 720.00	Patch: Unlock only works if default display is screen 0		
OSF440CDE-027	State: Supersedes patch OSF440CDE-015 (213.00) This patch corrects the following:		
	 Fixes a problem where when running the Common Desktop Environment (CDE) on a system with more than one graphics card and monitor (multihead), sometimes new windows were visible when the screen was locked. 		
	 Fixes a problem on multi-head systems in which the unlock display only works if the default display is screen 0. 		
Patch 723.00 OSF440-576	Patch: Fix for problems with Ladebug and TotalView debuggers State: Supersedes patches OSF440-321 (378.00), OSF440-556 (721.00) This patch corrects the following:		
	Fixes a kernel memory fault in procfs_get_s5_dir.		
	 Corrects a problem where attaching to a program with a debugger will cause periodic timers to be lost and will make the program hang. 		
	 Resolves problems encontered with the Ladebug and TotalView debuggers. 		
Patch 725.00	Patch: Security (SSRT0672U)		
OSF440-517	State: New A potential security vulnerability has been discovered where, under certain circumstances, system integrity may be compromised. This may be in the form of improper file or privilege management. Compaq has corrected this potential vulnerability.		
Patch 727.00	Patch: Fix for Korn shell hang		
OSF440-575	State: New This patch fixes a problem where the Korn shell (ksh) could hang if you pasted a large number of commands to it when it was running in a terminal emulator window (such as an xterm).		
Patch 729.00 OSF440X11-037	Patch: Fixes a memory leak in the X server State: Supersedes patch OSF440X11-027 (357.00) This patch corrects the following:		
	 Fixes a problem where the X server could core dump or get unaligned access errors when clients used the Multi-Buffering extension. 		
	 Fixes a memory leak in the X server that could occur when a client repeatedly created and destroyed buffers for the X Window System Multibuffering Extension (XmbufCreateBuffers/XmbufDestroyBuffers). 		
Patch 731.00 OSF440-531	Patch: Corrects a memory leak in the XTI socket code State: Supersedes patch OSF440-049 (43.00) This patch corrects the following:		
	 Fixes a problem with XTI over TCP/IP when tcp_sendspace and tcp_recvspace have been decreased to 1k. When sending 4k data (using t_snd), the call is successful but no data has been sent and no message is returned. 		
	Corrects a memory leak in the XTI socket code.		
Patch 733.00 OSF440-486	Patch: Fixes a problem with ATM signalling State: New This patch fixes a problem of ATM signalling going into "connection released" after a system reboot.		

Table 2-2:	Summary	of Base	Operating	System	Patches	(cont.)
------------	---------	---------	-----------	---------------	----------------	---------

Table 2–2: Summ	nary of Base Operating System Patches (cont.)
Patch 735.00 OSF440-523	Patch: Prevents Turbolaser panic with DE600 in pci slot 0 State: New This patch prevents a panic on TurboLaser systems with a DE600 in pci slot 0. Mis-identification of the DE600 in pci slot 0 causes data structure corruption. TurboLaser systems include the following:
	AlphaServer 8200 AlphaServer 8400 AlphaServer GS60 AlphaServer GS60E AlphaServer GS140
	A DE600 is a single-port 10/100 Mbps Fast Ethernet NIC.
Patch 737.00	Patch: dtpad does not allocate enough memory
OSF440CDE-028B	State: New This patch fixes a problem where, if dtpad cannot allocate enough memory, it will exit and leave a zero-length file in place of the file being edited.
Patch 739.00	Patch: Security (SSRT1-15, SSRT0713U)
OSF440-564	State: New A potential security vulnerability has been discovered where, under certain circumstances, system integrity may be compromised. This may be in the form of improper file or privilege management. Compaq has corrected this potential vulnerability.
Patch 741.00 OSF440-519	Patch: Security (SSRT0592U) State: Supersedes patches OSF440-241 (279.00), OSF440-287 (319.00) This patch corrects the following:
	 Fixes a problem with rdist(1) which consumes huge amounts of memory, and when there are a lot of symlinks in the fileset, it can simply fail to fully populate the remote site, or cause low-memory problems on the local machine.
	 A potential security vulnerability has been discovered where, under certain circumstances, system integrity may be compromised. This may be in the form of improper file or privilege management. Compaq has corrected this potential vulnerability.
_	 Corrects a problem in the rdist utility which was causing segmentation faults on files with more than one link.
Patch 744.00 OSF440-494	Patch: Security (SSRT0664U) State: Supersedes patches OSF440-178 (236.00), OSF440-524 (742.00) This patch corrects the following:
	 Fixes a problem that occurs when using ftp. When mget or nlist specify a filename with metacharacters and the mode is ASCII, the file is returned with <lf> as the end-of-file seperator. With this patch, files are returned with <cr><lf> as the end-of-file seperator.</lf></cr></lf>
	• Corrects a problem with the ftpd daemon which could result in PC ftp clients hanging when transferring some files in ASCII mode.
	 A potential security vulnerability has been discovered where, under certain circumstances, system integrity may be compromised. This may be in the form of improper file or privilege management. Compaq has corrected this potential vulnerability.

Patch 746.00 OSF440-538

Patch: Corrects a problem with joind

State: Supersedes patches OSF440-079 (158.00), OSF440-201 (253.00), OSF440-246 (282.00), OSF440-249 (285.00)

- Adds an error message to DHCP to inform a user that they may be using an outdated database. The message also points to the README for database conversion instructions.
- Fixes a problem of the joind daemon not appending the hostname to the load file specified in the bf flag in the /etc/bootptab file.
- Fixes a problem in which joind does not listen on interfaces configured with DECnet and returns "unaligned access" messages.
- Fixes a problem in which bprelay does not work properly and displays the following error message
 - bprelay[658]: can't find interface which received packet
- Corrects a problem with joind which caused it to respond to certain client dhcp requests via the wrong port.

Summary of TruCluster Software Patches

This chapter summarizes the TruCluster software patches included in Patch Kit-0006.

Table 3–1 lists patches that have been updated.

Table 3–2 provides a summary of patches.

Table 3–1: Updated TruCluster Software Patches

Patch IDs	Change Summary
Patch 80.00	New
Patches 2.00, 9.00, 10.00, 5.00, 13.00, 16.00, 17.00, 14.00, 29.00, 31.00, 38.00, 39.00, 47.00, 21.00, 49.00, 32.00, 43.00, 27.00, 48.00, 52.00, 53.00, 54.00, 55.00, 56.00, 57.00, 59.00	Patch 78.00
Patch 30.00	Patch 82.00

Table 3-2: Summary of TruCluster Patches

Patch IDs	Abstract	
Patch 4.00	Patch: Fix for Kernel Memory Fault On DRD Client Nodes	
TCR160-004	State: Existing	
	This patch fixes a kernel memory fault on the DRD client nodes just as or after the DRD server node has initiated MC2 hub failover.	
Patch 7.00	Patch: Fix for Reliable Datagram API	
TCR160-010	State: Supersedes patch TCR160-001 (1.00)	
	This patch corrects the following:	
	 Reliable Datagram (RDG) messaging support. 	
	 RDG: bug fix to the completion queue synchronization protocol. 	
Patch 8.00	Patch: doconfig may hang when running in TruCluster environment	
TCR160-011	State: Existing	
	This patch fixes two problems that could cause doconfig to appear to hang when running in a TruCluster environment.	
Patch 12.00	Patch: Fixes problem with Networker displaying characters	
TCR160-018	State: Existing	
	This patch corrects a problem with Networker displaying garbage characters following service names. It occurs when the service name is 8 characters or greater.	
Patch 33.00	Patch: Fix for drdadmin problems	
TCR160-037	State: Existing	
	This patch fixes various problems with drdadmin to be user friendly.	
Patch 34.00	Patch: Fixes a limitation in ase_reconfig_bus	
TCR160-038	State: Existing	
	This patch fixes a limitation in ase_reconfig_bus. Now up to 99 buses can be reconfigured with this command.	

Table 3–2: Sun	nmary of TruCluster Patches (cont.)
Patch 35.00 TCR160-039	Patch: LSM disk information not updated in ASE database State: Supersedes patch TCR160-030 (28.00) This patch corrects the following:
	 Fixes a problem that would cause an error from awk(1) when modifying an ASE service that contained a large number of LSM volumes. The error would prevent the service from being properly modified.
	 Fixes a problem where LSM disk information was not properly updated in the ASE database when volumes were removed from a disk service.
Patch 36.00	Patch: Fix for asedirector hang
TCR160-040	State: Existing This patch fixes a problem that could cause an NFS or Disk Service that has a hyphen (-) in the service name to end up unassigned after a disk failure. A side effect of the problem was that the asedirector would hang after the disk failure was corrected.
Patch 37.00	Patch: clu_ivp does not recognize Emulex adapter
TCR160-041	State: Existing This patch fixes a problem where the Emulex Fibre Channel adapter was not recognized by clu_ivp.
Patch 42.00	Patch: Processes may get referenced several times
TCR160-046	State: Supersedes patches TCR160-008 (6.00), TCR160-023 (15.00), TCR160-044 (40.00)
	This patch corrects the following:
	 Fixes a problem in which a cluster node can panic with the panic string "convert_lock: bad lock state".
	 Corrects a problem in which a failure in the session layer can cause DLM messages to become corrupt resulting in random DLM panic on the receiving member.
	 Fixes a problem that can cause a TruCluster member to panic during shutdown.
	 Fixes a bug where sometimes a certain shared sequence number will not be freed after use. It also fixes a problem where certain processes could get referenced several times.
Patch 61.00 TCR160-054B	Patch: Fixes problems with the clu_ivp script State: Supersedes patches TCR160-009B (22.00), TCR160-021B (23.00), TCR160-022B (24.00), TCR160-031B (25.00), TCR160-036B (50.00), TCR160-047B (51.00)
	This patch corrects the following:
	• This is a performance improvement in the startup of start scripts. It will reduce the necessary system calls to start the scripts.
	Corrects a problem with member add in a large environment.
	 Corrects a problem which causes asemgr to core dump when modifying a single drd service to add more than 200 devices.

Fixes a problem that caused aseagent or asehsm to core dump when starting NFS and Disk Services that contain several LSM

Corrects a problem that causes the ASE director to core dump

Fixes a problem with extraneous compiler warnings about strdup()

volumes.

during initialization.

function calls from ASE.

Patch 63.00 TCR160-064	Patch: Node crashes when holding an mc-api lock State: Supersedes patches TCR160-029 (20.00), TCR160-050 (46.00) This patch corrects the following:
	 Fixes a hang problem in a cluster when two nodes communicate using the mc-api and a third node, not involved in the calculation, is rebooted.
	 Fixes a problem that can cause a panic in mcs_wait_cluster_event() when using the Memory Channel API.
	 Fixes a problem with the Memory Channel API where, when a node crashes holding an mc-api lock, under certain circumstances the lock will not be released after the node crashes.
Patch 65.00 TCR160-063	Patch: Unable to remove LSM volumes from DRD service State: Supersedes patch TCR160-003 (3.00) This patch corrects the following:
	 Fixes a problem where DRD permissions could be lost if a service is modified more than once.
	 Fixes a problem that prevented the removal of LSM volumes from a DRD service. The problem occurs when there are multiple LSM diskgroups in the service, and all of the volumes from one diskgroup were removed.
Patch 67.00 TCR160-054C	Patch: clu_ivp script enhancements State: New
1CK100-054C	This patch fixes three problems with the clu_ivp script:
	The script now checks to be sure that the cluster members are listed in the /etc/hosts file.
	• The script no longer copies /var/adm/messages to /tmp. Copying the messages file to /tmp could result in the filesystem becoming full, and clu_ivp exiting with an error.
	 The script now checks the /var/adm/messages file for shared busses if none are listed in the configuration file.
Patch 70.00	Patch: TruCluster Production server hangs during boot
TCR160-056	State: Supersedes patches TCR160-017 (11.00), TCR160-027 (19.00), TCR160-032 (26.00), TCR160-062 (68.00)
	This patch corrects the following:
	 Fixes a problem where both nodes in a cluster will panic at the same time with a simple_lock timeout panic.
	 Fixes a kernel memory fault in rm_lock_update_retry().
	 Fixes a problem which can cause the following panic:
	panic (cpu 0): rm_update_single_lock_miss: time limit exceeded
	 Fixes a problem that could cause an error to be returned when the Cluster software should wait until a global lock is freed.
	 Fixes a problem that could cause a TruCluster Production server member to hang during boot, and can cause a "simple lock time limit exceeded" panic.
Patch 72.00	Patch: Error msg if system contained unsupported controllers
1 attil 12.00	2 access 21101 mag is system contained unsupported controllers

TCR160-067

State: New

This patch fixes a problem that caused an error message to be printed if the system contained unsupported controllers. The error message will now only be printed when running the command in verbose mode.

Table 3-2: Summary of TruCluster Patches (cont.)

Patch 74.00	Patch: Access mode for a directory not set to default State: Supersedes patches TCR160-045 (41.00), TCR160-048 (44.00), TCR160-049 (45.00)		
TCR160-061			
	This patch corrects the following:		
	 Fixes a problem that caused the setting of the force unmount option to be incorrectly displayed by the asemgr utility. 		
	 Fixes a problem that caused shell errors if an invalid mount option was specified via the asemgr menu. 		
	 Fixes a problem that caused the device name for a UNIX File System (UFS) to not be displayed when modifying the force unmount option via the asemgr utility. 		
	 Fixes a problem that caused the access mode for a directory to not get set to the default after modifying them via asemgr. 		
Patch 76.00	Patch: Problem causes mountd to exit without error		
TCR160-055	State: New		
	This patch fixes a problem that could cause mountd to exit without error during boot.		

Table 3–2: Summary of TruCluster Patches (cont.)

Patch 78.00 TCR160-071

Patch: Fixes a problem that causes asedirector to core dump **State:** Supersedes patches TCR160-002 (2.00), TCR160-009A (9.00), TCR160-016 (10.00), TCR160-007 (5.00), TCR160-021A (13.00), TCR160-024 (16.00), TCR160-025 (17.00), TCR160-022A (14.00), TCR160-033 (29.00), TCR160-035 (31.00), TCR160-042 (38.00), TCR160-043 (39.00), TCR160-051 (47.00), TCR160-031A (21.00), TCR160-053 (49.00), TCR160-036A (32.00), TCR160-047A (43.00), TCR160-028 (27.00), TCR160-052 (48.00), TCR160-065 (52.00), TCR160-066 (53.00), TCR160-058 (54.00), TCR160-060 (55.00), TCR160-054A (56.00), TCR160-057 (57.00), TCR160-059 (59.00) This patch corrects the following

- Fixes two problems in the asedirector:
 - An ASE command timeout problem encountered by large ASE services.
 - An incorrect decision made by the asedirector as a result of a failed inquire services command.
- This is a performance improvement in the startup of start scripts. It will reduce the necessary system calls to start the scripts.
- Fixes a problem where the Host Status Monitor (asehsm) incorrectly reports a network down (HSM_NI_STATUS DOWN) if the counters for the network interface get zeroed.
- Fixes an ASE problem where, under certain circumstances, the service scripts could cause the ASE agent to loop during a start or stop service.
- Corrects a problem with member add in a large environment.
- Corrects a problem with TruCluster Available Server or Production Server cluster in which services have been started with elevated priority and scheduling algorithm. Under significant load this could lead to intermittent network and cluster problems.
- Fixes a problem which caused a service not to start when there was a short network failure. This was seen only with long running stop scripts and special network configurations.
- Corrects a problem which causes asemgr to core dump when modifying a single drd service to add more than 200 devices.
- Fixes a problem that caused aseagent or asehsm to core dump when starting NFS and Disk Services that contain several LSM volumes.
- Fixes a problem where the asemgr will hang as it continuously create and kill multiple directors.
- Corrects a problem that causes the ASE director to core dump during initialization.
- Corrects a problem where modifying a service with a large number of DRDs will fail and a "could not malloc" message is seen in the daemon.log file.
- Fixes a problem where the MEMBER_STATE variable always is shown as BOOTING instead of RUNNING. After first installing TCR, there is no way to have scripts know the MEMBER_STATE. This problem is cleared on a reboot.
- Corrects a problem in which a network cable failure that corrects within 7 seconds of the failure can leave the services in a bad state.
- Fixes a problem that caused the asemgr to get a memory fault when adding multiple services in a row.
- Fixes a problem with extraneous compiler warnings about strdup() function calls from ASE.

Table 3-2: Summary of TruCluster Patches (cont.)

Patch 78.00 continued

- Fixes a problem that caused the asemgr utility to not run when called from a program that is owned by root and has the setuid bit turned on.
- Fixes a problem that can cause the Cluster MIB daemon (cnxmibd) to core dump in Available Server environments.
- Fixes a problem which caused an error message to be logged for the cnxmibd even though no error had occurred.
- Fixes two issues with clusters:
 - When a cluster is brought up with ASE off, other members report it as UP and RUNNING instead of UP and UNKNOWN.
 - When a restricted service is running on a member, and asemember stop or aseam stop is executed, the service status is still reported as the member name, instead of Unassigned.
- Fixes a problem where timeout values of greater than 30 seconds in /etc/hsm.conf would cause ASE agent to fail at start up.
- Fixes a bug where the aseagent will occasionally core dump on a SCSI bus hang.
- Fixes a problem that caused the asemgr to report the wrong status for a service.
- This patch fixes the following problems with the clu_ivp script:

The script now checks to be sure that the cluster members are listed in the /etc/hosts file, and it no longer copies /var/adm/messages to /tmp. Copying the messages file to /tmp could result in the filesystem becoming full, and clu_ivp exiting with an error. The clu_ivp script now also checks the /var/adm/messages file for shared busses if none are listed in the configuration file.

- Fixes a problem that could cause the asedirector to core dump.
- Fixes a problem that caused the asemgr to report that a disk, or mount point, was in multiple services when modifying a service name.
- Fixes a problem with the ASE application from reporting an incorrect status while booting, after installation or while re-initializing the database.

Patch 80.00 TCR160-070

Patch: Fixes problem with ASE_SNMPD_IGNORE_DISKS **State:** New

This patch fixes a problem with the ASE_SNMPD_IGNORE_DISKS feature. After specifying a disk to ignore, the ASE service stop and add commands result in conflicting data. While the daemon.log reports apparent success ("hrm_dsk.c will ignore /dev/rzb10") the error log reports a failure that indicates that the device is NOT being ignored (CAM "unit reserved error").

Patch 82.00 TCR160-068

Patch: Fix for boot failure on a cluster

State: Supersedes patch TCR160-034 (30.00)

- Fixes a problem which caused a boot failure on a cluster with a large number of shared SCSI buses.
- Fixes a problem in clustered systems. It reduces the occurrences of tmv2_notify_cbf error messages in the errlog.