

YAMAHA CORPORATION February 29, 2000

Release Notes for DS-XG Driver Version 5.12.01.2225

1. Basic Information

Supported OS: Windows98 Second Edition, Windows2000

Supported Language:

U.S. English, Japanese, French, German, Italian, Spanish, Simplified Chinese, Traditional Chinese, Korean, Brazilian Portuguese, Swedish

Supported Hardware:

YMF724(DS-1) A, B, C, D, E, F ver.

YMF740(DS-1L) A, B, C ver.

YMF744(DS-1S) A, B ver.

YMF754(DS-1E)

2. File Information

1) Driver

ds1.cpl	(2000/02/28 294,912byte)
ds1.sys	(2000/02/28 2,486,149byte)
ds1bra.hlp	(2000/02/18 32,787byte)
ds1eng.hlp	(2000/02/18 25,352byte)
ds1fre.hlp	(2000/02/18 33,610byte)
ds1ger.hlp	(2000/02/18 31,989byte)
ds1ita.hlp	(2000/02/18 32,495byte)
ds1jpn.hlp	(2000/02/18 24,400byte)
ds1kor.hlp	(2000/02/18 27,688byte)
ds1sch.hlp	(2000/02/18 20,922byte)
ds1spa.hlp	(2000/02/18 34,175byte)
ds1swe.hlp	(2000/02/18 31,578byte)
ds1tch.hlp	(2000/02/18 20,819byte)
dslaunch.exe	(1999/12/07 262,144byte)
dsxaplib.dll	(1999/12/07 57,344byte)
dsxgwave.tbl	(1999/04/02 2,417,445byte)
dsxmixer.exe	(1999/12/07 331,776byte)
nlds1s0w.inf	(2000/02/29 51,496byte)

2) Docker

¥Docker¥ydsxgdk.inf (2000/02/29 2,529byte)

¥Docker¥ydsxgdk.sys (2000/02/28 7,897byte)

3. Difference from the Last Release (ver. 4.10.2223)

- (1) Added the proprietary power management function.
- (2) Changed the file names of the help files so that they have unique names depending on the language supported.
- (3) Changed the version numbering from “4.10.0.2xxx” to “5.12.01.2xxx”, to meet the DirectX requirement.
- (4) Changed the DDK to the release version.
- (5) Fixed the problem with the direct digital recording function on YMF754(DS-1E).
- (6) Changed the Device ID of the Gameport to PNPB02F.
- (7) Fixed the problem that the system sometimes froze when repeating Log On/Log Off on Win2K, with the Control Panel open.
- (8) Fixed the problem that it became impossible to remove ds1.cpl once the Control Panel was opened after starting up the Win2K.